

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| Manufacturer                                    | Manufacturers Model Name           | Software Version               |
|---|------------------------------------|--------------------------------|
| \$STUDY.APPLICATIONENTITY.SDM.MANUFACTURER.NAME | \$study.applicationEntity.sdm.name |                                |
| \$STUDY.APPLICATIONENTITY.SDM.MANUFACTURER.NAME | \$study.applicationEntity.sdm.name | 2.2                            |
| ACUO  | Unknown Model                      | Unknown                        |
| AGFA  | ClinApps                           | 3.3.19                         |
| AGFA HEALTHCARE                                 | IMPAX                              | 6.6.1.3525/6.6.1.3505          |
| AMICAS INC.                                     | Aquilion                           | V4.77ER007                     |
| AMICAS INC.                                     | Aquilion                           | V4.83ER002                     |
| AMICAS INC.                                     | Aquilion                           | V6.06ER016                     |
| AMICAS INC.                                     | Aquilion ONE                       | V6.00ER007                     |
| AMICAS INC.                                     | Biograph64                         | VG60A                          |
| AMICAS INC.                                     | Emotion 16 (2007)                  | syngo CT 2014A                 |
| AMICAS INC.                                     | Ingenuity CT                       | 3.5.5                          |
| AMICAS INC.                                     | SOMATOM Definition AS              | syngo CT 2011A                 |
| AMICAS INC.                                     | SOMATOM Definition AS              | syngo CT 2012B                 |
| AMICAS INC.                                     | SOMATOM Definition AS              | syngo CT 2013B                 |
| AMICAS INC.                                     | SOMATOM Definition AS              | syngo CT VA48A                 |
| AMICAS INC.                                     | SOMATOM Definition AS+             | syngo CT 2012B                 |
| AMICAS INC.                                     | SOMATOM Perspective                | syngo CT VC30 - easyIQ version |
| AMICAS INC.                                     | Sensation Open                     | syngo CT 2014A                 |
| AMICAS INC.                                     | syngo.via.VA30A                    | Unknown                        |
| AMICAS INC.                                     | syngo.via.VB10A                    | Unknown                        |
| AMICAS-NSC                                      | V6_6.4.7.103271                    | 6.4.7.103271                   |
| BAYER HEALTHCARE LLC                            | Certegra                           | 4.50.18016.1655                |
| BAYER HEALTHCARE LLC                            | Certegra                           | 4.60.18267.1406                |
| BAYER HEALTHCARE LLC                            | Certegra                           | 4.70.19273.1249                |
| BAYER MEDICAL CARE INC.                         | Certegra                           | 4.1.15040.1504                 |
| BAYER MEDICAL CARE INC.                         | Certegra                           | 4.20.15162.1339                |
| BAYER MEDICAL CARE INC.                         | Certegra                           | 4.21.15335.1605                |
| BAYER MEDICAL CARE INC.                         | Certegra                           | 4.32.16057.1717                |
| BAYER MEDICAL CARE INC.                         | Certegra                           | 4.40.16307.1030                |
| CANON   | DR-C225                            | V1.0                           |
| CANON MEDICAL SYSTEMS                           | Aquilion ONE                       | V10.00ER006                    |
| CANON MEDICAL SYSTEMS                           | Aquilion ONE                       | V10.00ER007                    |
| CANON MEDICAL SYSTEMS                           | Aquilion ONE                       | V10.00ER009                    |
| CANON MEDICAL SYSTEMS                           | Aquilion ONE                       | V10.00ER011                    |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| Manufacturer                              | Manufacturers Model Name    | Software Version                              |
|---|-----------------------------|---|
| CANON MEDICAL SYSTEMS                     | Aquilion ONE                | V8.90ER008                                    |
| CANON MEDICAL SYSTEMS                     | Aquilion Prime SP           | V10.20ER001                                   |
| CANON MEDICAL SYSTEMS                     | Aquilion Prime SP           | V10.20ER002                                   |
| CANON MEDICAL SYSTEMS                     | Aquilion Prime SP           | V10.20ER004                                   |
| CANON MEDICAL SYSTEMS                     | Celesteion                  | V6.51ER006                                    |
| CARESTREAM                                | OnSight 3D Extremity System | 1.0   |
| CARESTREAM                                | OnSight 3D Extremity System | 1.1   |
| CEDARA                                    | Unknown Model               | Unknown                                       |
| CIRCLECVI                                 | Unknown Model               | Unknown                                       |
| CIRCLECVI                                 | Unknown Model               | cvi42 5.3.6                                   |
| COM.SERPHYDOSE.CORE.BEANS.MANUFACTURER@7E | BrightSpeed Elite 16 Slices |   |
| COM.SERPHYDOSE.CORE.BEANS.MANUFACTURER@7E | Discovery ST 16             |   |
| COM.SERPHYDOSE.CORE.BEANS.MANUFACTURER@7E | LightSpeed 16               |   |
| COM.SERPHYDOSE.CORE.BEANS.MANUFACTURER@7E | LightSpeed VCT              |   |
| COM.SERPHYDOSE.CORE.BEANS.MANUFACTURER@7E | Optima CT660                |   |
| CURVEBEAM                                 | PedCat                      | 7.0.0.9                                       |
| DR SYSTEMS, INC.                          | Unknown Model               | 11.0B455D12641                                |
| EXCELA HEALTH DICOM SCANNING APPLICATION  | APT                         | Unknown                                       |
| FUJIFILM MEDICAL SYSTEMS USA, INC.        | SOMATOM Definition AS+      | syngo CT VA48A                                |
| FUJIFILM MEDICAL SYSTEMS USA, INC.        | Sensation 64                | syngo CT 2014A                                |
| FUJIFILM MEDICAL SYSTEMS USA, INC.        | Unknown Model               | Unknown                                       |
| GE MEDICAL SYSTEMS                        | Aquilion PRIME              |   |
| GE MEDICAL SYSTEMS                        | BRIVO CT325                 |   |
| GE MEDICAL SYSTEMS                        | BrightSpeed                 |   |
| GE MEDICAL SYSTEMS                        | BrightSpeed                 | 07MW11.10                                     |
| GE MEDICAL SYSTEMS                        | BrightSpeed                 | 17BW11.2                                      |
| GE MEDICAL SYSTEMS                        | BrightSpeed                 | Unknown                                       |
| GE MEDICAL SYSTEMS                        | BrightSpeed                 | bj_sles_cl.81                                 |
| GE MEDICAL SYSTEMS                        | BrightSpeed                 | mach.4  |
| GE MEDICAL SYSTEMS                        | BrightSpeed                 | qin.20  |
| GE MEDICAL SYSTEMS                        | BrightSpeed                 | qin.3   |
| GE MEDICAL SYSTEMS                        | BrightSpeed                 | tandem_mf.14                                  |
| GE MEDICAL SYSTEMS                        | BrightSpeed                 | tandem_qin.5                                  |
| GE MEDICAL SYSTEMS                        | BrightSpeed                 | tandem_qin_540_build_5.tandem_qin_540_build_5 |
| GE MEDICAL SYSTEMS                        | BrightSpeed 16              |   |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b> |
|---------------------|---------------------------------|-------------------------|
| GE MEDICAL SYSTEMS  | BrightSpeed Elite 16 Slices     |                         |
| GE MEDICAL SYSTEMS  | BrightSpeed QX/i                |                         |
| GE MEDICAL SYSTEMS  | BrightSpeed QX/i                | Unknown                 |
| GE MEDICAL SYSTEMS  | BrightSpeed QX/i                | qin.20                  |
| GE MEDICAL SYSTEMS  | BrightSpeed S                   |                         |
| GE MEDICAL SYSTEMS  | BrightSpeed S                   | 10BW27.7                |
| GE MEDICAL SYSTEMS  | BrightSpeed S                   | Soft1234                |
| GE MEDICAL SYSTEMS  | BrightSpeed S                   | Unknown                 |
| GE MEDICAL SYSTEMS  | BrightSpeed S                   | qin.3                   |
| GE MEDICAL SYSTEMS  | Brilliance-64                   |                         |
| GE MEDICAL SYSTEMS  | CT 860                          | 18IW45.44               |
| GE MEDICAL SYSTEMS  | Centricity Digital Hardcopy     | 8.0                     |
| GE MEDICAL SYSTEMS  | Centricity Radiology RA 600     | 8.0                     |
| GE MEDICAL SYSTEMS  | Discovery 600                   |                         |
| GE MEDICAL SYSTEMS  | Discovery 600                   | Unknown                 |
| GE MEDICAL SYSTEMS  | Discovery 600                   | kh_xar.30               |
| GE MEDICAL SYSTEMS  | Discovery 600                   | pet_velocity.53         |
| GE MEDICAL SYSTEMS  | Discovery 610                   |                         |
| GE MEDICAL SYSTEMS  | Discovery 610                   | Unknown                 |
| GE MEDICAL SYSTEMS  | Discovery 610                   | pet_coreload.44         |
| GE MEDICAL SYSTEMS  | Discovery 610                   | pet_mfk.56              |
| GE MEDICAL SYSTEMS  | Discovery 670                   |                         |
| GE MEDICAL SYSTEMS  | Discovery 690                   |                         |
| GE MEDICAL SYSTEMS  | Discovery 690                   | Unknown                 |
| GE MEDICAL SYSTEMS  | Discovery 690                   | kh_xar.30               |
| GE MEDICAL SYSTEMS  | Discovery 690                   | pet_mict_plus.44        |
| GE MEDICAL SYSTEMS  | Discovery 690                   | pet_velocity.53         |
| GE MEDICAL SYSTEMS  | Discovery 710                   |                         |
| GE MEDICAL SYSTEMS  | Discovery 710                   | Unknown                 |
| GE MEDICAL SYSTEMS  | Discovery 710                   | pet_coreload.44         |
| GE MEDICAL SYSTEMS  | Discovery 710                   | pet_coreload.87         |
| GE MEDICAL SYSTEMS  | Discovery CT                    |                         |
| GE MEDICAL SYSTEMS  | Discovery CT                    | 16MW34.4                |
| GE MEDICAL SYSTEMS  | Discovery CT                    | 17BW13.17               |
| GE MEDICAL SYSTEMS  | Discovery CT                    | 17BW50.7B               |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b>                           |
|---------------------|---------------------------------|---|
| GE MEDICAL SYSTEMS  | Discovery CT                    | Unknown   |
| GE MEDICAL SYSTEMS  | Discovery CT                    | bj_sles_hde6b_release.4                           |
| GE MEDICAL SYSTEMS  | Discovery CT                    | sles_hde.198                                      |
| GE MEDICAL SYSTEMS  | Discovery CT590 RT              |   |
| GE MEDICAL SYSTEMS  | Discovery CT590 RT              | 15BW19.22   |
| GE MEDICAL SYSTEMS  | Discovery CT590 RT              | Unknown   |
| GE MEDICAL SYSTEMS  | Discovery CT590 RT              | qin.3   |
| GE MEDICAL SYSTEMS  | Discovery CT590 RT              | rt_bjcl.4   |
| GE MEDICAL SYSTEMS  | Discovery CT750 HD              |   |
| GE MEDICAL SYSTEMS  | Discovery CT750 HD              | 11MW44.10   |
| GE MEDICAL SYSTEMS  | Discovery CT750 HD              | 11MW44.11   |
| GE MEDICAL SYSTEMS  | Discovery CT750 HD              | 13MW24.2  |
| GE MEDICAL SYSTEMS  | Discovery CT750 HD              | 13MW24.7  |
| GE MEDICAL SYSTEMS  | Discovery CT750 HD              | 14MW24.7  |
| GE MEDICAL SYSTEMS  | Discovery CT750 HD              | 16MW34.4  |
| GE MEDICAL SYSTEMS  | Discovery CT750 HD              | 17BW50.7B   |
| GE MEDICAL SYSTEMS  | Discovery CT750 HD              | Unknown   |
| GE MEDICAL SYSTEMS  | Discovery CT750 HD              | bj_sles_hde6b_release.4                           |
| GE MEDICAL SYSTEMS  | Discovery CT750 HD              | gmp_hde.72  |
| GE MEDICAL SYSTEMS  | Discovery CT750 HD              | gmp_hde.74  |
| GE MEDICAL SYSTEMS  | Discovery CT750 HD              | gsi_mict_plus.145                                 |
| GE MEDICAL SYSTEMS  | Discovery CT750 HD              | gsi_mict_plus.32                                  |
| GE MEDICAL SYSTEMS  | Discovery CT750 HD              | sles_hde.132                                      |
| GE MEDICAL SYSTEMS  | Discovery CT750 HD              | sles_hde.170                                      |
| GE MEDICAL SYSTEMS  | Discovery CT750 HD              | sles_hde.198                                      |
| GE MEDICAL SYSTEMS  | Discovery CT750 HD              | sles_hde.84                                       |
| GE MEDICAL SYSTEMS  | Discovery CT750 HD              | sles_hde3.5                                       |
| GE MEDICAL SYSTEMS  | Discovery HD 750                |   |
| GE MEDICAL SYSTEMS  | Discovery IQ                    |   |
| GE MEDICAL SYSTEMS  | Discovery IQ                    | Unknown   |
| GE MEDICAL SYSTEMS  | Discovery IQ                    | pet_comet.81                                      |
| GE MEDICAL SYSTEMS  | Discovery IQ                    | pet_odyssey.28                                    |
| GE MEDICAL SYSTEMS  | Discovery IQ                    | pet_odyssey.66                                    |
| GE MEDICAL SYSTEMS  | Discovery IQ                    | pet_odyssey.69                                    |
| GE MEDICAL SYSTEMS  | Discovery LS                    | LightSpeedAppsct_dls2_m5_cc5_1.2__R2.9N.IRIX646.5 |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b>                      |
|---------------------|---------------------------------|--|
| GE MEDICAL SYSTEMS  | Discovery LS                    | LightSpeedAppsct_dst_dls_1.7_R2.9N.IRIX646.5 |
| GE MEDICAL SYSTEMS  | Discovery MI                    |  |
| GE MEDICAL SYSTEMS  | Discovery MI                    | Unknown                                      |
| GE MEDICAL SYSTEMS  | Discovery MI                    | pet_col_bb.31                                |
| GE MEDICAL SYSTEMS  | Discovery MI                    | pet_columbia.103                             |
| GE MEDICAL SYSTEMS  | Discovery MI                    | pet_columbia.179                             |
| GE MEDICAL SYSTEMS  | Discovery MI                    | pet_columbia.184                             |
| GE MEDICAL SYSTEMS  | Discovery MI DR                 |  |
| GE MEDICAL SYSTEMS  | Discovery MI DR                 | Unknown                                      |
| GE MEDICAL SYSTEMS  | Discovery MI DR                 | pet_blackbird.28                             |
| GE MEDICAL SYSTEMS  | Discovery MI DR                 | pet_col_bb.31                                |
| GE MEDICAL SYSTEMS  | Discovery MI DR                 | pet_columbia.179                             |
| GE MEDICAL SYSTEMS  | Discovery NM/CT 670             |  |
| GE MEDICAL SYSTEMS  | Discovery RT                    |  |
| GE MEDICAL SYSTEMS  | Discovery RT                    | 16BW32.11                                    |
| GE MEDICAL SYSTEMS  | Discovery RT                    | 17BW49.23                                    |
| GE MEDICAL SYSTEMS  | Discovery RT                    | Unknown                                      |
| GE MEDICAL SYSTEMS  | Discovery RT                    | rt_bjcl.46                                   |
| GE MEDICAL SYSTEMS  | Discovery RT                    | rt_bjcl.83                                   |
| GE MEDICAL SYSTEMS  | Discovery RX                    |  |
| GE MEDICAL SYSTEMS  | Discovery RX                    | Unknown                                      |
| GE MEDICAL SYSTEMS  | Discovery RX                    | dm09_dvctsp1.23                              |
| GE MEDICAL SYSTEMS  | Discovery RX                    | dm09_hl2sp1.23                               |
| GE MEDICAL SYSTEMS  | Discovery ST                    |  |
| GE MEDICAL SYSTEMS  | Discovery ST                    | Unknown                                      |
| GE MEDICAL SYSTEMS  | Discovery ST                    | dm09_hl2sp1.23                               |
| GE MEDICAL SYSTEMS  | Discovery ST 16                 |  |
| GE MEDICAL SYSTEMS  | Discovery STE                   |  |
| GE MEDICAL SYSTEMS  | Discovery STE                   | 41.04  |
| GE MEDICAL SYSTEMS  | Discovery STE                   | dm09_dvctsp1.23                              |
| GE MEDICAL SYSTEMS  | Discovery STE                   | dm09_hl2sp1.23                               |
| GE MEDICAL SYSTEMS  | DoseWatch                       |  |
| GE MEDICAL SYSTEMS  | DoseWatch                       | 2.2  |
| GE MEDICAL SYSTEMS  | DoseWatch                       | 2.3  |
| GE MEDICAL SYSTEMS  | Dual Energy Viewer              | 2.00-0M                                      |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| Manufacturer       | Manufacturers Model Name | Software Version                |
|--------------------|--------------------------|---------------------------------|
| GE MEDICAL SYSTEMS | Dual Energy Viewer       | 2.00-0N                         |
| GE MEDICAL SYSTEMS | Dual Energy Viewer       | 2.10-0J                         |
| GE MEDICAL SYSTEMS | FILMER_3.0               | pet_coreload.44                 |
| GE MEDICAL SYSTEMS | GEHC CT Scanner          |                                 |
| GE MEDICAL SYSTEMS | HiSpeed CT/i             | 05                              |
| GE MEDICAL SYSTEMS | HiSpeed NX/i             | 7.03                            |
| GE MEDICAL SYSTEMS | HiSpeed QX/i             |                                 |
| GE MEDICAL SYSTEMS | HiSpeed QX/i             | LightSpeedverrel                |
| GE MEDICAL SYSTEMS | INFINIA                  | 2.005.007.15\HARDWARE_VERSION_1 |
| GE MEDICAL SYSTEMS | INFINIA                  | 2.105.030.18                    |
| GE MEDICAL SYSTEMS | LightSpeed               |                                 |
| GE MEDICAL SYSTEMS | LightSpeed               | 07MW11.10                       |
| GE MEDICAL SYSTEMS | LightSpeed               | Unknown                         |
| GE MEDICAL SYSTEMS | LightSpeed               | qin.3                           |
| GE MEDICAL SYSTEMS | LightSpeed 16            |                                 |
| GE MEDICAL SYSTEMS | LightSpeed Plus          |                                 |
| GE MEDICAL SYSTEMS | LightSpeed Plus          | 07MW11.10                       |
| GE MEDICAL SYSTEMS | LightSpeed Plus          | LightSpeedApps2.4.2_H2.4M5      |
| GE MEDICAL SYSTEMS | LightSpeed Plus          | LightSpeedApps308i.2_H3.1M5     |
| GE MEDICAL SYSTEMS | LightSpeed Plus          | LightSpeedverrel                |
| GE MEDICAL SYSTEMS | LightSpeed Plus          | Unknown                         |
| GE MEDICAL SYSTEMS | LightSpeed Pro 16        |                                 |
| GE MEDICAL SYSTEMS | LightSpeed Pro 16        | 07MW11.10                       |
| GE MEDICAL SYSTEMS | LightSpeed Pro 16        | Unknown                         |
| GE MEDICAL SYSTEMS | LightSpeed Pro 32        |                                 |
| GE MEDICAL SYSTEMS | LightSpeed Pro 32        | 07MW18.4                        |
| GE MEDICAL SYSTEMS | LightSpeed Pro 32        | Unknown                         |
| GE MEDICAL SYSTEMS | LightSpeed QX/i          |                                 |
| GE MEDICAL SYSTEMS | LightSpeed QX/i          | 07MW11.10                       |
| GE MEDICAL SYSTEMS | LightSpeed QX/i          | LightSpeedApps2.4.2_H2.4M5      |
| GE MEDICAL SYSTEMS | LightSpeed QX/i          | Unknown                         |
| GE MEDICAL SYSTEMS | LightSpeed RT            |                                 |
| GE MEDICAL SYSTEMS | LightSpeed RT            | 07MW11.10                       |
| GE MEDICAL SYSTEMS | LightSpeed RT16          |                                 |
| GE MEDICAL SYSTEMS | LightSpeed RT16          | 08BW44.1                        |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b>       |
|---------------------|---------------------------------|-------------------------------|
| GE MEDICAL SYSTEMS  | LightSpeed RT16                 | 10BW27.7                      |
| GE MEDICAL SYSTEMS  | LightSpeed RT16                 | Unknown                       |
| GE MEDICAL SYSTEMS  | LightSpeed RT16                 | qin.3                         |
| GE MEDICAL SYSTEMS  | LightSpeed RT16                 | rt_bjcl.35                    |
| GE MEDICAL SYSTEMS  | LightSpeed Ultra                |                               |
| GE MEDICAL SYSTEMS  | LightSpeed Ultra                | 07MW11.10                     |
| GE MEDICAL SYSTEMS  | LightSpeed Ultra                | LightSpeedApps308l.2_H3.1M5   |
| GE MEDICAL SYSTEMS  | LightSpeed Ultra                | LightSpeedverrel              |
| GE MEDICAL SYSTEMS  | LightSpeed Ultra                | qin_perenna.20                |
| GE MEDICAL SYSTEMS  | LightSpeed VCT                  |                               |
| GE MEDICAL SYSTEMS  | LightSpeed VCT                  | 07MW18.4                      |
| GE MEDICAL SYSTEMS  | LightSpeed VCT                  | 08MW33.2                      |
| GE MEDICAL SYSTEMS  | LightSpeed VCT                  | 09MW08.11                     |
| GE MEDICAL SYSTEMS  | LightSpeed VCT                  | 12HW14.6                      |
| GE MEDICAL SYSTEMS  | LightSpeed VCT                  | 13HW31.8                      |
| GE MEDICAL SYSTEMS  | LightSpeed VCT                  | 16HW36.4                      |
| GE MEDICAL SYSTEMS  | LightSpeed VCT                  | Unknown                       |
| GE MEDICAL SYSTEMS  | LightSpeed VCT                  | VCTME3.0                      |
| GE MEDICAL SYSTEMS  | LightSpeed VCT                  | coreload.118                  |
| GE MEDICAL SYSTEMS  | LightSpeed VCT                  | dualkv_vctc.9                 |
| GE MEDICAL SYSTEMS  | LightSpeed VCT                  | gmp_vct.21                    |
| GE MEDICAL SYSTEMS  | LightSpeed VCT                  | gmp_vct.26                    |
| GE MEDICAL SYSTEMS  | LightSpeed VCT                  | gmp_vct.42                    |
| GE MEDICAL SYSTEMS  | LightSpeed VCT                  | vct_zeta.4                    |
| GE MEDICAL SYSTEMS  | LightSpeed Xtra                 |                               |
| GE MEDICAL SYSTEMS  | LightSpeed Xtra                 | 10BW27.7                      |
| GE MEDICAL SYSTEMS  | LightSpeed Xtra                 | qin.3                         |
| GE MEDICAL SYSTEMS  | LightSpeed16                    |                               |
| GE MEDICAL SYSTEMS  | LightSpeed16                    | 07MW11.10                     |
| GE MEDICAL SYSTEMS  | LightSpeed16                    | 17BW11.2                      |
| GE MEDICAL SYSTEMS  | LightSpeed16                    | 6.4                           |
| GE MEDICAL SYSTEMS  | LightSpeed16                    | LightSpeedApps405l.2_H4.0M5   |
| GE MEDICAL SYSTEMS  | LightSpeed16                    | LightSpeedApps405l.3_H4.0M5.1 |
| GE MEDICAL SYSTEMS  | LightSpeed16                    | LightSpeedverrel              |
| GE MEDICAL SYSTEMS  | LightSpeed16                    | Unknown                       |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b>                            |
|---------------------|---------------------------------|--|
| GE MEDICAL SYSTEMS  | LightSpeed16                    | qin.13   |
| GE MEDICAL SYSTEMS  | LightSpeed16                    | qin.3  |
| GE MEDICAL SYSTEMS  | LightSpeed16                    | qin_perenna.20                                     |
| GE MEDICAL SYSTEMS  | Optima 560                      |  |
| GE MEDICAL SYSTEMS  | Optima 560                      | pet_mfk.44   |
| GE MEDICAL SYSTEMS  | Optima 560 FX                   |  |
| GE MEDICAL SYSTEMS  | Optima 560 FX                   | pet_mfk.44   |
| GE MEDICAL SYSTEMS  | Optima CT520 Series             |  |
| GE MEDICAL SYSTEMS  | Optima CT520 Series             | 17BW24.1   |
| GE MEDICAL SYSTEMS  | Optima CT520 Series             | bj_sles_cl.68                                      |
| GE MEDICAL SYSTEMS  | Optima CT520 Series             | kl_dod.10  |
| GE MEDICAL SYSTEMS  | Optima CT540                    |  |
| GE MEDICAL SYSTEMS  | Optima CT540                    | 17BW24.1   |
| GE MEDICAL SYSTEMS  | Optima CT540                    | 18BW23.2   |
| GE MEDICAL SYSTEMS  | Optima CT540                    | 6.4  |
| GE MEDICAL SYSTEMS  | Optima CT540                    | Unknown  |
| GE MEDICAL SYSTEMS  | Optima CT540                    | bj_sles_cl.68                                      |
| GE MEDICAL SYSTEMS  | Optima CT540                    | bj_sles_cl.86                                      |
| GE MEDICAL SYSTEMS  | Optima CT540                    | nm_tangE_mar.10                                    |
| GE MEDICAL SYSTEMS  | Optima CT540                    | nm_tang_build.nm_tang_build                        |
| GE MEDICAL SYSTEMS  | Optima CT540                    | qin.3  |
| GE MEDICAL SYSTEMS  | Optima CT540                    | tandem_D670_ES.tandem_D670_ES                      |
| GE MEDICAL SYSTEMS  | Optima CT540                    | tandem_qin_540_build_sp2_5.tandem_qin_540_build_sp |
| GE MEDICAL SYSTEMS  | Optima CT580                    |  |
| GE MEDICAL SYSTEMS  | Optima CT580                    | Unknown  |
| GE MEDICAL SYSTEMS  | Optima CT580                    | qin.3  |
| GE MEDICAL SYSTEMS  | Optima CT580                    | rt_bjcl.35   |
| GE MEDICAL SYSTEMS  | Optima CT580                    | rt_bjcl.4  |
| GE MEDICAL SYSTEMS  | Optima CT660                    |  |
| GE MEDICAL SYSTEMS  | Optima CT660                    | 12HW28.8   |
| GE MEDICAL SYSTEMS  | Optima CT660                    | 13HW38.14  |
| GE MEDICAL SYSTEMS  | Optima CT660                    | 14HW30.3   |
| GE MEDICAL SYSTEMS  | Optima CT660                    | 15HW13.7   |
| GE MEDICAL SYSTEMS  | Optima CT660                    | 15HW25.2   |
| GE MEDICAL SYSTEMS  | Optima CT660                    | 16HW45.1   |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**



**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b> |
|---------------------|---------------------------------|-------------------------|
| GE MEDICAL SYSTEMS  | Optima CT660                    | 6.4                     |
| GE MEDICAL SYSTEMS  | Optima CT660                    | Unknown                 |
| GE MEDICAL SYSTEMS  | Optima CT660                    | cj.37                   |
| GE MEDICAL SYSTEMS  | Optima CT660                    | cj2_0m3sp2.15           |
| GE MEDICAL SYSTEMS  | Optima CT660                    | cj2_5m3sp4.5            |
| GE MEDICAL SYSTEMS  | Optima CT660                    | cj2_5m3sp5.5            |
| GE MEDICAL SYSTEMS  | Optima CT660                    | cj3_6m3a_qr.11          |
| GE MEDICAL SYSTEMS  | Optima CT660                    | cj_kl.17                |
| GE MEDICAL SYSTEMS  | Optima CT660                    | cj_kl.59                |
| GE MEDICAL SYSTEMS  | Optima CT660                    | coreload.81             |
| GE MEDICAL SYSTEMS  | QX/i                            |                         |
| GE MEDICAL SYSTEMS  | Revolution ACT                  |                         |
| GE MEDICAL SYSTEMS  | Revolution ACT                  | 17BW35.13               |
| GE MEDICAL SYSTEMS  | Revolution ACTs                 |                         |
| GE MEDICAL SYSTEMS  | Revolution Apex                 |                         |
| GE MEDICAL SYSTEMS  | Revolution Apex                 | 19MW38.10               |
| GE MEDICAL SYSTEMS  | Revolution Apex                 | 20MW01.16               |
| GE MEDICAL SYSTEMS  | Revolution CT                   |                         |
| GE MEDICAL SYSTEMS  | Revolution CT                   | 14MW14.29               |
| GE MEDICAL SYSTEMS  | Revolution CT                   | 15MW03.12               |
| GE MEDICAL SYSTEMS  | Revolution CT                   | 15MW43.7                |
| GE MEDICAL SYSTEMS  | Revolution CT                   | 16MW14.13               |
| GE MEDICAL SYSTEMS  | Revolution CT                   | 17MW20.16               |
| GE MEDICAL SYSTEMS  | Revolution CT                   | 17MW20.22               |
| GE MEDICAL SYSTEMS  | Revolution CT                   | 18MW18.30               |
| GE MEDICAL SYSTEMS  | Revolution CT                   | 19MW09.27               |
| GE MEDICAL SYSTEMS  | Revolution CT                   | 19MW22.14               |
| GE MEDICAL SYSTEMS  | Revolution CT                   | 20MW01.16               |
| GE MEDICAL SYSTEMS  | Revolution CT                   | REVO 1.0                |
| GE MEDICAL SYSTEMS  | Revolution CT                   | Unknown                 |
| GE MEDICAL SYSTEMS  | Revolution CT                   | revo1_m3.171            |
| GE MEDICAL SYSTEMS  | Revolution CT                   | revo1_m3_mdcp1.4        |
| GE MEDICAL SYSTEMS  | Revolution CT                   | revo_1.5_m3a.46         |
| GE MEDICAL SYSTEMS  | Revolution CT                   | revo_1.5_m3b_xt.53      |
| GE MEDICAL SYSTEMS  | Revolution CT                   | revo_1.5_m3d.9          |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b> |
|---------------------|---------------------------------|-------------------------|
| GE MEDICAL SYSTEMS  | Revolution CT                   | revo_ct_21a.33          |
| GE MEDICAL SYSTEMS  | Revolution CT                   | revo_ct_21b.32          |
| GE MEDICAL SYSTEMS  | Revolution CT                   | revo_ct_22a.32          |
| GE MEDICAL SYSTEMS  | Revolution EVO                  |                         |
| GE MEDICAL SYSTEMS  | Revolution EVO                  | 14HW17.4                |
| GE MEDICAL SYSTEMS  | Revolution EVO                  | 15HW13.7                |
| GE MEDICAL SYSTEMS  | Revolution EVO                  | 16HW14.9                |
| GE MEDICAL SYSTEMS  | Revolution EVO                  | 16HW45.1                |
| GE MEDICAL SYSTEMS  | Revolution EVO                  | 18HW46.17               |
| GE MEDICAL SYSTEMS  | Revolution EVO                  | 19HW19.4                |
| GE MEDICAL SYSTEMS  | Revolution EVO                  | Unknown                 |
| GE MEDICAL SYSTEMS  | Revolution EVO                  | cj3_6m3a_qr.11          |
| GE MEDICAL SYSTEMS  | Revolution EVO                  | cj_digital.32           |
| GE MEDICAL SYSTEMS  | Revolution EVO                  | cj_kl.59                |
| GE MEDICAL SYSTEMS  | Revolution EVO                  | cj_kl.89                |
| GE MEDICAL SYSTEMS  | Revolution Frontier             |                         |
| GE MEDICAL SYSTEMS  | Revolution Frontier             | 17BW50.12C              |
| GE MEDICAL SYSTEMS  | Revolution Frontier             | 17BW50.13C              |
| GE MEDICAL SYSTEMS  | Revolution Frontier             | 18BW35.31               |
| GE MEDICAL SYSTEMS  | Revolution Frontier             | Unknown                 |
| GE MEDICAL SYSTEMS  | Revolution Frontier             | bj_sles_hde.56          |
| GE MEDICAL SYSTEMS  | Revolution Frontier             | bj_sles_hde6c_sp.1      |
| GE MEDICAL SYSTEMS  | Revolution GSI                  |                         |
| GE MEDICAL SYSTEMS  | Revolution GSI                  | 14MW24.7                |
| GE MEDICAL SYSTEMS  | Revolution GSI                  | Unknown                 |
| GE MEDICAL SYSTEMS  | Revolution GSI                  | sles_hde.132            |
| GE MEDICAL SYSTEMS  | Revolution HD                   |                         |
| GE MEDICAL SYSTEMS  | Revolution HD                   | 14MW24.7                |
| GE MEDICAL SYSTEMS  | Revolution HD                   | 15MW42.11               |
| GE MEDICAL SYSTEMS  | Revolution HD                   | 15MW42.7                |
| GE MEDICAL SYSTEMS  | Revolution HD                   | 16MW34.4                |
| GE MEDICAL SYSTEMS  | Revolution HD                   | 17BW13.17               |
| GE MEDICAL SYSTEMS  | Revolution HD                   | 17BW50.12C              |
| GE MEDICAL SYSTEMS  | Revolution HD                   | 17BW50.13C              |
| GE MEDICAL SYSTEMS  | Revolution HD                   | 17BW50.7B               |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| Manufacturer       | Manufacturers Model Name | Software Version                                  |
|--------------------|--------------------------|---|
| GE MEDICAL SYSTEMS | Revolution HD            | 18BW35.31   |
| GE MEDICAL SYSTEMS | Revolution HD            | Unknown   |
| GE MEDICAL SYSTEMS | Revolution HD            | bj_sles_hde.56                                    |
| GE MEDICAL SYSTEMS | Revolution HD            | bj_sles_hde6b_release.1                           |
| GE MEDICAL SYSTEMS | Revolution HD            | bj_sles_hde6b_release.4                           |
| GE MEDICAL SYSTEMS | Revolution HD            | bj_sles_hde6c_sp.1                                |
| GE MEDICAL SYSTEMS | Revolution HD            | bj_sles_hde6c_sp.12                               |
| GE MEDICAL SYSTEMS | Revolution HD            | sles_hde.132                                      |
| GE MEDICAL SYSTEMS | Revolution HD            | sles_hde.170                                      |
| GE MEDICAL SYSTEMS | Revolution HD            | sles_hde.178                                      |
| GE MEDICAL SYSTEMS | Revolution HD            | sles_hde.197                                      |
| GE MEDICAL SYSTEMS | Revolution HD            | sles_hde.198                                      |
| GE MEDICAL SYSTEMS | Revolution HD            | sles_hde6.37                                      |
| GE MEDICAL SYSTEMS | SOMATOM Definition       |   |
| GE MEDICAL SYSTEMS | SOMATOM Definition Edge  |   |
| GE MEDICAL SYSTEMS | SOMATOM Force            |   |
| GE MEDICAL SYSTEMS | SafeCT                   | 07MW11.10\1.2.26.2\MV_GID_2\AP reformats/Abdomen/ |
| GE MEDICAL SYSTEMS | SafeCT                   | 07MW11.10\1.2.26.2\MV_GID_2\Chest/Neck/Chest (De  |
| GE MEDICAL SYSTEMS | SafeCT                   | 07MW11.10\1.2.26.2\MV_GID_2\Chest Hi-Res/Chest (D |
| GE MEDICAL SYSTEMS | SafeCT                   | 07MW11.10\1.2.26.2\MV_GID_3\AP 2.5/Abdomen/Pelvis |
| GE MEDICAL SYSTEMS | SafeCT                   | 07MW18.4\1.2.26.2\MV_GID_1\Abdomen/Pelvis With Co |
| GE MEDICAL SYSTEMS | SafeCT                   | 07MW18.4\1.2.26.2\MV_GID_1\Chest REF/Chest (Defau |
| GE MEDICAL SYSTEMS | SafeCT                   | 07MW18.4\1.2.26.2\MV_GID_1\Sinus Reformats bone/S |
| GE MEDICAL SYSTEMS | SafeCT                   | 07MW18.4\1.2.26.2\MV_GID_2\Abdomen/Pelvis With Co |
| GE MEDICAL SYSTEMS | SafeCT                   | dm09_dvctsp1.23\1.2.26.2\MV_GID_1\Chest/Chest (De |
| GE MEDICAL SYSTEMS | SafeCT                   | dm09_dvctsp1.23\1.2.26.2\MV_GID_1\Pancreas Portal |
| GE MEDICAL SYSTEMS | SafeCT                   | dm09_hl2sp1.23\1.2.26.2\MV_GID_1\Chest Hi-Res/Che |
| GE MEDICAL SYSTEMS | SafeCT                   | dm09_hl2sp1.23\1.2.26.2\MV_GID_1\Head 2.5/Head (D |
| GE MEDICAL SYSTEMS | SafeCT                   | dm09_hl2sp1.23\1.2.26.2\MV_GID_3\AP reformats/Abd |
| GE MEDICAL SYSTEMS | SafeCT                   | dm09_hl2sp1.23\1.2.26.2\MV_GID_3\abdomen/pelvis N |
| GE MEDICAL SYSTEMS | SafeCT                   | dm09_hl2sp1.23\1.2.40.12\MV_GID_1\Head Reformats/ |
| GE MEDICAL SYSTEMS | SafeCT                   | gmp_vct.42\1.2.26.2\MV_GID_1\Chest REF/Chest (Def |
| GE MEDICAL SYSTEMS | SafeCT                   | gmp_vct.42\1.2.26.2\MV_GID_2\AP urogram W/C/Abdom |
| GE MEDICAL SYSTEMS | SafeCT                   | gmp_vct.42\1.2.40.12\MV_GID_1\Chest Angio for PE/ |
| GE MEDICAL SYSTEMS | SafeCT                   | gmp_vct.42\1.2.40.12\MV_GID_2\Chest REF/Chest (De |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| Manufacturer       | Manufacturers Model Name     | Software Version                                  |
|--------------------|------------------------------|---|
| GE MEDICAL SYSTEMS | SafeCT                       | gmp_vct.42\1.2.40.12\MV_GID_2\Pancreas NonCon Pre |
| GE MEDICAL SYSTEMS | SafeCT                       | qin.3\1.2.18\lung 5mm/Chest Sharp +               |
| GE MEDICAL SYSTEMS | TFD-3000B                    |   |
| GE MEDICAL SYSTEMS | Tandem_Optima_640            | 1.003.222.0HARDWARE_VERSION_1                     |
| GE MEDICAL SYSTEMS | Tandem_Optima_640            | 1.003.429.0HARDWARE_VERSION_1                     |
| GE MEDICAL SYSTEMS | Unknown Model                | Unknown   |
| GENERAL ELECTRIC   | BrightSpeed Elite 16 Slices  |   |
| GENERAL ELECTRIC   | BrightSpeed Elite 4/8 Slices |   |
| GENERAL ELECTRIC   | BrightSpeed QX/i             |   |
| GENERAL ELECTRIC   | Discovery CT590 RT           |   |
| GENERAL ELECTRIC   | Discovery CT750 HD           |   |
| GENERAL ELECTRIC   | Discovery IQ                 |   |
| GENERAL ELECTRIC   | Discovery MI                 |   |
| GENERAL ELECTRIC   | Discovery NM/CT 670          |   |
| GENERAL ELECTRIC   | Discovery NM/CT 870 DR       |   |
| GENERAL ELECTRIC   | Discovery PET/CT 600         |   |
| GENERAL ELECTRIC   | Discovery PET/CT 690/600     |   |
| GENERAL ELECTRIC   | Discovery PET/CT 710         |   |
| GENERAL ELECTRIC   | Discovery ST                 |   |
| GENERAL ELECTRIC   | Discovery ST 16              |   |
| GENERAL ELECTRIC   | Discovery STE                |   |
| GENERAL ELECTRIC   | LightSpeed 16                |   |
| GENERAL ELECTRIC   | LightSpeed 16                | 2.2   |
| GENERAL ELECTRIC   | LightSpeed Plus              |   |
| GENERAL ELECTRIC   | LightSpeed Pro16             |   |
| GENERAL ELECTRIC   | LightSpeed Pro32             |   |
| GENERAL ELECTRIC   | LightSpeed QX/i              |   |
| GENERAL ELECTRIC   | LightSpeed RT16              |   |
| GENERAL ELECTRIC   | LightSpeed Ultra             |   |
| GENERAL ELECTRIC   | LightSpeed VCT               |   |
| GENERAL ELECTRIC   | LightSpeed VCT               | 2.2   |
| GENERAL ELECTRIC   | LightSpeed VCT XT            |   |
| GENERAL ELECTRIC   | LightSpeed VCT XTe           |   |
| GENERAL ELECTRIC   | Optima CT540                 |   |
| GENERAL ELECTRIC   | Optima CT580                 |   |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b>         | <b>Manufacturers Model Name</b> | <b>Software Version</b>              |
|-----------------------------|---------------------------------|--------------------------------------|
| GENERAL ELECTRIC            | Optima CT660                    |                                      |
| GENERAL ELECTRIC            | Optima CT660                    | 2.2                                  |
| GENERAL ELECTRIC            | Revolution CT                   |                                      |
| GENERAL ELECTRIC            | Revolution EVO                  |                                      |
| GENERAL ELECTRIC            | Revolution EVO                  | 2.2                                  |
| GENERAL ELECTRIC            | Revolution GSI                  |                                      |
| GENERAL ELECTRIC            | Revolution GSI                  | 2.2                                  |
| GENERAL ELECTRIC            | Revolution HD                   |                                      |
| HITACHI                     | CXR4                            | 0005                                 |
| HITACHI                     | SCENARIA                        | 0005                                 |
| HITACHI MEDICAL CORPORATION |                                 | 0005                                 |
| HITACHI MEDICAL CORPORATION | ECLOS                           | 0005                                 |
| HITACHI MEDICAL CORPORATION | SCENARIA                        | 0005                                 |
| HITACHI MEDICAL CORPORATION | Supria                          | 0005                                 |
| HITACHI, LTD.               | SCENARIA                        | 0005                                 |
| HITACHI, LTD.               | SCENARIA View                   | 0005                                 |
| HITACHI, LTD.               | Supria                          | 0005                                 |
| HYLAND                      | Unknown Model                   | V1.0                                 |
| INFINITT                    | SD                              | Unknown                              |
| INTELERAD MEDICAL SYSTEMS   | InteleViewer                    | 4-10-1-P123                          |
| INTELERAD MEDICAL SYSTEMS   | InteleViewer                    | 4-12-1-P451                          |
| INTELERAD MEDICAL SYSTEMS   | InteleViewer                    | 4-15-1-P136                          |
| INTELERAD MEDICAL SYSTEMS   | InteleViewer                    | 4-6-1-P182                           |
| INTELERAD MEDICAL SYSTEMS   | InteleViewer                    | 4-7-1-P190                           |
| INTELERAD MEDICAL SYSTEMS   | InteleViewer                    | 4-7-1-P205                           |
| ISCHEMAVIEW                 | RAPID                           | 4.8.3.5-rapid4_8_3_5final-0-g205c046 |
| ISCHEMAVIEW                 | RAPID                           | 5.0.2                                |
| ISCHEMAVIEW                 | RAPID                           | 5.1.1-rapid5_0final-374-g62927e4     |
| LEXMARK                     | Unknown Model                   | V1.0                                 |
| LIFEIMAGENOMINATION         | Unknown Model                   | Unknown                              |
| LIFEIMAGENOTIFY             | Unknown Model                   | Unknown                              |
| LIGHTSPEED VCT              | LightSpeed VCT                  | 12HW14.6                             |
| MCKESSON                    | ALI                             | Format=1                             |
| MEDRAD, INC.                | Certegra                        | 2.5.0.1                              |
| MEDRAD, INC.                | Certegra                        | 3.3.12324.1358                       |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b> |
|---------------------|---------------------------------|-------------------------|
| MEDRAD, INC.        | Certegra                        | 3.5.13255.1019          |
| MEDRAD, INC.        | Certegra                        | 3.6.14016.1145          |
| MEDTRONIC           | O-Arm MVS                       | 3.2.0                   |
| MEDTRONIC           | O-arm MVS O2                    | 4.0.2                   |
| MEDTRONIC           | O-arm MVS O2                    | 4.1.0                   |
| MEDWEB              | None                            | Unknown                 |
| MINDWAYS QCTPRO     | Unknown Model                   | Unknown                 |
| MOBIUS IMAGING, LLC | AIRO                            | 1.1.2.1                 |
| MOBIUS IMAGING, LLC | AIRO                            | 1.2.0.2                 |
| MOBIUS IMAGING, LLC | AIRO                            | 1.2.1.3                 |
| MOBIUS IMAGING, LLC | AIRO                            | 1.3.0.5                 |
| MOBIUS IMAGING, LLC | AIRO                            | 2.1.0.2                 |
| NEUROLOGICA         | BodyTom                         | 1.07.00                 |
| NEUROLOGICA         | BodyTom                         | 1.07.01                 |
| NEUROLOGICA         | BodyTom                         | 1.08.02                 |
| NEUROLOGICA         | CereTom                         |                         |
| NEUROLOGICA         | CereTom                         | 05.02                   |
| NEUROLOGICA         | CereTom                         | 05.05                   |
| NEUROLOGICA         | CereTom                         | 05.07                   |
| NEUROLOGICA         | CereTom                         | 05.09                   |
| NEUROLOGICA         | CereTom                         | 05.11                   |
| NEUROLOGICA         | CereTom                         | 05.12                   |
| NEUROLOGICA         | CereTom                         | 05.13.00                |
| NEUROLOGICA         | CereTom                         | 6.01                    |
| NEUROLOGICA         | CereTom                         | 6.02.01                 |
| NEUROLOGICA         | CereTom                         | 6.02.02                 |
| NEUROLOGICA         | CereTom                         | 6.03                    |
| NEUROLOGICA         | CereTom                         | 6.04.01                 |
| NEUROLOGICA         | CereTom                         | 6.04.01 P1              |
| NEUROLOGICA         | CereTom                         | 6.04.01 P2              |
| NEUROLOGICA         | CereTom                         | 6.04.02                 |
| NEUROLOGICA         | CereTom                         | 6.04.05                 |
| NEUROLOGICA         | CereTom                         | 6.04.08                 |
| NEUROLOGICA         | CereTom                         | Unknown                 |
| NMS                 | NeuViz 128                      | 1.0.8.5219+P01          |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b> |
|---------------------|---------------------------------|-------------------------|
| NMS                 | NeuViz 128                      | 1.0.8.5219+P07          |
| NMS                 | NeuViz 128                      | 1.0.8.5219110           |
| NMS                 | NeuViz 128                      | 1.0.8.5219195           |
| NMS                 | NeuViz 128                      | NeuViz 128 1.0          |
| NMS                 | NeuViz 64                       |                         |
| NMS                 | NeuViz 64                       | 1.0.6.3339+P03          |
| NMS                 | NeuViz 64                       | 1.0.6.3339060           |
| NMS                 | NeuViz 64                       | NeuViz 64e 1.0          |
| NMS                 | NeuViz 64 En                    | 1.0.7.4164165           |
| NMS                 | NeuViz 64 En                    | NeuViz 64 En 1.0        |
| NMS                 | NeuViz 64e                      | 1.0.6.3339+P03          |
| NMS                 | NeuViz 64e                      | 1.0.6.3339060           |
| NMS                 | NeuViz 64i                      | 1.0.6.3339+P03          |
| NMS                 | NeuViz 64i                      | 1.0.6.3339060           |
| PACSGEAR            | Unknown Model                   | 3.1.1.3                 |
| PACSGEAR            | Unknown Model                   | 3.2.0.3                 |
| PACSGEAR            | Unknown Model                   | 3.2.3.1                 |
| PACSGEAR            | Unknown Model                   | 3.3.1.13                |
| PACSGEAR            | Unknown Model                   | 4.0                     |
| PACSGEAR            | Unknown Model                   | 5.1                     |
| PACSGEAR            | Unknown Model                   | Unknown                 |
| PACSGEAR            | Unknown Model                   | V1.0                    |
| PHILIPS             |                                 | 2.3.0                   |
| PHILIPS             |                                 | 4.1                     |
| PHILIPS             | Big Bore                        | 4.8                     |
| PHILIPS             | Brilliance 10                   | 2.3.0                   |
| PHILIPS             | Brilliance 16                   |                         |
| PHILIPS             | Brilliance 16                   | 2.3.0                   |
| PHILIPS             | Brilliance 16                   | 3.5.3                   |
| PHILIPS             | Brilliance 16                   | 3.6.0                   |
| PHILIPS             | Brilliance 16                   | 3.6.2                   |
| PHILIPS             | Brilliance 16                   | 3.6.5                   |
| PHILIPS             | Brilliance 16                   | 3.6.6                   |
| PHILIPS             | Brilliance 16                   | 3.6.6.13504             |
| PHILIPS             | Brilliance 16                   | 3.6.7                   |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b> |
|---------------------|---------------------------------|-------------------------|
| PHILIPS             | Brilliance 16                   | 3.6.8                   |
| PHILIPS             | Brilliance 16                   | 4.1.0.0                 |
| PHILIPS             | Brilliance 16P                  |                         |
| PHILIPS             | Brilliance 16P                  | 2.2.6                   |
| PHILIPS             | Brilliance 16P                  | 2.3.0                   |
| PHILIPS             | Brilliance 16P                  | 2.3.5                   |
| PHILIPS             | Brilliance 16P                  | 3.6.0                   |
| PHILIPS             | Brilliance 16P                  | 3.6.2                   |
| PHILIPS             | Brilliance 16P                  | 3.6.6                   |
| PHILIPS             | Brilliance 16P                  | 3.6.7                   |
| PHILIPS             | Brilliance 16P                  | 3.6.8                   |
| PHILIPS             | Brilliance 40                   | 2.3.0                   |
| PHILIPS             | Brilliance 40                   | 2.3.5                   |
| PHILIPS             | Brilliance 6                    | 2.3.0                   |
| PHILIPS             | Brilliance 6                    | 2.3.5                   |
| PHILIPS             | Brilliance 64                   |                         |
| PHILIPS             | Brilliance 64                   | 2.2.1                   |
| PHILIPS             | Brilliance 64                   | 2.3.0                   |
| PHILIPS             | Brilliance 64                   | 2.4.0                   |
| PHILIPS             | Brilliance 64                   | 2.4.5                   |
| PHILIPS             | Brilliance 64                   | 2.6.0                   |
| PHILIPS             | Brilliance 64                   | 2.6.1                   |
| PHILIPS             | Brilliance 64                   | 2.6.2                   |
| PHILIPS             | Brilliance 64                   | 3.5.0                   |
| PHILIPS             | Brilliance 64                   | 3.5.1.21003             |
| PHILIPS             | Brilliance 64                   | 3.5.1.22003             |
| PHILIPS             | Brilliance 64                   | 3.5.2                   |
| PHILIPS             | Brilliance 64                   | 3.5.3                   |
| PHILIPS             | Brilliance 64                   | 3.5.4                   |
| PHILIPS             | Brilliance 64                   | 3.5.4.21001             |
| PHILIPS             | Brilliance 64                   | 3.5.4.22001             |
| PHILIPS             | Brilliance 64                   | 3.5.5                   |
| PHILIPS             | Brilliance 64                   | 3.5.5.22007             |
| PHILIPS             | Brilliance 64                   | 3.6.2                   |
| PHILIPS             | Brilliance 64                   | 3.6.5                   |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**



**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b> |
|---------------------|---------------------------------|-------------------------|
| PHILIPS             | Brilliance 64                   | 3.6.6                   |
| PHILIPS             | Brilliance 64                   | 3.6.7                   |
| PHILIPS             | Brilliance 64                   | 3.6.8                   |
| PHILIPS             | Brilliance 64                   | 4.0                     |
| PHILIPS             | Brilliance 64                   | 4.1                     |
| PHILIPS             | Brilliance 64                   | 4.1.0.0                 |
| PHILIPS             | Brilliance 64                   | Unknown                 |
| PHILIPS             | Brilliance Big Bore             |                         |
| PHILIPS             | Brilliance Big Bore             | 2.3.0                   |
| PHILIPS             | Brilliance Big Bore             | 2.3.5                   |
| PHILIPS             | Brilliance Big Bore             | 2.4.10                  |
| PHILIPS             | Brilliance Big Bore             | 2.4.7                   |
| PHILIPS             | Brilliance Big Bore             | 2.4.8                   |
| PHILIPS             | Brilliance Big Bore             | 2.4.9                   |
| PHILIPS             | Brilliance Big Bore             | 3.5.2                   |
| PHILIPS             | Brilliance Big Bore             | 3.5.3                   |
| PHILIPS             | Brilliance Big Bore             | 3.5.4                   |
| PHILIPS             | Brilliance Big Bore             | 3.5.4.17001             |
| PHILIPS             | Brilliance Big Bore             | 3.5.5                   |
| PHILIPS             | Brilliance Big Bore             | 3.6.0                   |
| PHILIPS             | Brilliance Big Bore             | 3.6.2                   |
| PHILIPS             | Brilliance Big Bore             | 3.6.6                   |
| PHILIPS             | Brilliance Big Bore             | 3.6.6.17204             |
| PHILIPS             | Brilliance Big Bore             | 3.6.7                   |
| PHILIPS             | Brilliance Big Bore             | 3.6.8                   |
| PHILIPS             | Brilliance Big Bore             | 4.2                     |
| PHILIPS             | Brilliance iCT                  | 2.5.0                   |
| PHILIPS             | Brilliance iCT                  | 3.0.0                   |
| PHILIPS             | Brilliance iCT                  | 3.2.4                   |
| PHILIPS             | Brilliance-16                   |                         |
| PHILIPS             | Brilliance-40                   |                         |
| PHILIPS             | Brilliance-64                   |                         |
| PHILIPS             | Brilliance16                    |                         |
| PHILIPS             | Brilliance16                    | 2.0.2                   |
| PHILIPS             | Brilliance16                    | 2.3.5                   |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b> |
|---------------------|---------------------------------|-------------------------|
| PHILIPS             | Brilliance16                    | 2.3.6                   |
| PHILIPS             | Brilliance16                    | 3.6.6                   |
| PHILIPS             | Brilliance16                    | 3.6.7                   |
| PHILIPS             | Brilliance16                    | 3.6.8                   |
| PHILIPS             | GEMINI LXL                      | 2.3.0                   |
| PHILIPS             | GEMINI TF                       |                         |
| PHILIPS             | GEMINI TF Big Bore              | 2.3.0                   |
| PHILIPS             | GEMINI TF Big Bore              | 2.3.8                   |
| PHILIPS             | GEMINI TF TOF 16                | 2.3.0                   |
| PHILIPS             | GEMINI TF TOF 64                |                         |
| PHILIPS             | GEMINI TF TOF 64                | 2.3.0                   |
| PHILIPS             | GEMINI TF TOF 64                | 2.3.8                   |
| PHILIPS             | GeminiGXL 16                    |                         |
| PHILIPS             | GeminiGXL 16                    | 2.0.0                   |
| PHILIPS             | GeminiGXL 16                    | 2.3.0                   |
| PHILIPS             | IQon - Spectral CT              |                         |
| PHILIPS             | IQon - Spectral CT              | 4.7                     |
| PHILIPS             | IQon - Spectral CT              | 4.7.5                   |
| PHILIPS             | IQon - Spectral CT              | 4.7.7                   |
| PHILIPS             | Incisive CT                     | CHESS4_5                |
| PHILIPS             | Ingenuity CT                    |                         |
| PHILIPS             | Ingenuity CT                    | 3.5.0                   |
| PHILIPS             | Ingenuity CT                    | 3.5.1.25003             |
| PHILIPS             | Ingenuity CT                    | 3.5.2                   |
| PHILIPS             | Ingenuity CT                    | 3.5.4                   |
| PHILIPS             | Ingenuity CT                    | 3.5.5                   |
| PHILIPS             | Ingenuity CT                    | 3.5.7                   |
| PHILIPS             | Ingenuity CT                    | 3.6.2                   |
| PHILIPS             | Ingenuity CT                    | 3.6.6                   |
| PHILIPS             | Ingenuity CT                    | 3.6.7                   |
| PHILIPS             | Ingenuity CT                    | 3.6.8                   |
| PHILIPS             | Ingenuity CT                    | 4.0                     |
| PHILIPS             | Ingenuity CT                    | 4.1                     |
| PHILIPS             | Ingenuity CT                    | Unknown                 |
| PHILIPS             | Ingenuity Core                  |                         |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b>            |
|---------------------|---------------------------------|------------------------------------|
| PHILIPS             | Ingenuity Core                  | 4.1                                |
| PHILIPS             | Ingenuity Core 128              | 4.1                                |
| PHILIPS             | Ingenuity Flex                  | 3.6.6                              |
| PHILIPS             | Ingenuity TF PET/CT             | 4.0                                |
| PHILIPS             | Ingenuity TF PET/CT             | 4.1                                |
| PHILIPS             | IntelliSpace PACS Radiology     | Version 4.4.516.1 Build 4.4.2405.3 |
| PHILIPS             | IntelliSpace PACS Radiology     | Version 4.4.540.4 Build 4.4.3141.0 |
| PHILIPS             | IntelliSpace Portal             | 10.2.22.3925                       |
| PHILIPS             | IntelliSpace Portal             | 10.2.30.6771                       |
| PHILIPS             | MX 16-Slice                     | MX 16-slice 1.1                    |
| PHILIPS             | MX 16-slice                     | MX16_2_0                           |
| PHILIPS             | Precedence 16P                  | 2.0.0                              |
| PHILIPS             | TruFlight Select                | 2.3.0                              |
| PHILIPS             | Unknown Model                   | Unknown                            |
| PHILIPS             | Vereos PET/CT                   | 4.1                                |
| PHILIPS             | eCT                             | 3.5.0                              |
| PHILIPS             | iCT 128                         | 3.0.1                              |
| PHILIPS             | iCT 128                         | 3.2.0                              |
| PHILIPS             | iCT 128                         | 3.2.1.19001                        |
| PHILIPS             | iCT 128                         | 3.2.4                              |
| PHILIPS             | iCT 256                         |                                    |
| PHILIPS             | iCT 256                         | 2.2                                |
| PHILIPS             | iCT 256                         | 3.0.0                              |
| PHILIPS             | iCT 256                         | 3.0.1                              |
| PHILIPS             | iCT 256                         | 3.2.0                              |
| PHILIPS             | iCT 256                         | 3.2.3                              |
| PHILIPS             | iCT 256                         | 3.2.3.19002                        |
| PHILIPS             | iCT 256                         | 3.2.4                              |
| PHILIPS             | iCT 256                         | 4.1                                |
| PHILIPS             | iCT 256                         | Unknown                            |
| PHILIPS             | iCT SP                          |                                    |
| PHILIPS             | iCT SP                          | 4.1                                |
| PNMS                | MX 16                           | MX 16-slice 1.1                    |
| PNMS                | NeuViz 16                       | NeuViz 16 1.1                      |
| PNMS                | PHILIPS MX16                    | MX 16-slice 1.1                    |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b> |
|---------------------|---------------------------------|-------------------------|
| SAMSUNG             | OmniTom                         | OmniTom 2.2.7.0         |
| SEGAMI              | Oasis                           | Unknown                 |
| SIEMENS             |                                 | VA40C                   |
| SIEMENS             |                                 | syngo CT 2006A          |
| SIEMENS             |                                 | syngo CT 2006G          |
| SIEMENS             |                                 | syngo CT 2010A          |
| SIEMENS             |                                 | syngo CT 2011A          |
| SIEMENS             |                                 | syngo CT 2012B          |
| SIEMENS             |                                 | syngo CT 2012B.1.05_P00 |
| SIEMENS             |                                 | syngo CT VA48A          |
| SIEMENS             |                                 | syngo MI.PET/CT 2012A   |
| SIEMENS             | 1080                            | PET/CT 2007C            |
| SIEMENS             | AQNET                           |                         |
| SIEMENS             | AXIOM-Artis                     |                         |
| SIEMENS             | AXIOM-Artis                     | VC21B 150407            |
| SIEMENS             | Biograph 128                    | VG50A                   |
| SIEMENS             | Biograph 128                    | VG51C                   |
| SIEMENS             | Biograph 128                    | VG60A                   |
| SIEMENS             | Biograph 16                     | 6.6.2                   |
| SIEMENS             | Biograph 16                     | 6.7                     |
| SIEMENS             | Biograph 16                     | 6.7.2                   |
| SIEMENS             | Biograph 16                     | 6.7.3                   |
| SIEMENS             | Biograph 16                     | syngo CT 2009E          |
| SIEMENS             | Biograph 20                     |                         |
| SIEMENS             | Biograph 20                     | VG50A                   |
| SIEMENS             | Biograph 20                     | VG51A                   |
| SIEMENS             | Biograph 20                     | VG51C                   |
| SIEMENS             | Biograph 20                     | VG60A                   |
| SIEMENS             | Biograph 40                     |                         |
| SIEMENS             | Biograph 40                     | 6.7                     |
| SIEMENS             | Biograph 40                     | 6.7.2                   |
| SIEMENS             | Biograph 40                     | 6.7.3                   |
| SIEMENS             | Biograph 40                     | VG50A                   |
| SIEMENS             | Biograph 40                     | VG51B                   |
| SIEMENS             | Biograph 40                     | VG51C                   |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b> |
|---------------------|---------------------------------|-------------------------|
| SIEMENS             | Biograph 40                     | VG60A                   |
| SIEMENS             | Biograph 40                     | syngo CT 2006A          |
| SIEMENS             | Biograph 6                      |                         |
| SIEMENS             | Biograph 6                      | 6.6.2                   |
| SIEMENS             | Biograph 6                      | 6.7                     |
| SIEMENS             | Biograph 6                      | 6.7.2                   |
| SIEMENS             | Biograph 6                      | 6.7.3                   |
| SIEMENS             | Biograph 6                      | syngo CT 2006A          |
| SIEMENS             | Biograph 6                      | syngo CT 2009E          |
| SIEMENS             | Biograph 64                     |                         |
| SIEMENS             | Biograph 64                     | 6.7                     |
| SIEMENS             | Biograph 64                     | 6.7.2                   |
| SIEMENS             | Biograph 64                     | 6.7.3                   |
| SIEMENS             | Biograph 64                     | VG50A                   |
| SIEMENS             | Biograph 64                     | VG51A                   |
| SIEMENS             | Biograph 64                     | VG51B                   |
| SIEMENS             | Biograph 64                     | VG51C                   |
| SIEMENS             | Biograph 64                     | VG60A                   |
| SIEMENS             | Biograph 64                     | syngo CT 2006A          |
| SIEMENS             | Biograph Horizon                | VJ10A                   |
| SIEMENS             | Biograph Horizon                | VJ10B                   |
| SIEMENS             | Biograph Horizon                | VJ20A                   |
| SIEMENS             | Biograph Horizon                | VJ20B                   |
| SIEMENS             | Biograph Horizon                | VJ21A                   |
| SIEMENS             | Biograph Horizon                | VJ21B                   |
| SIEMENS             | Biograph128                     |                         |
| SIEMENS             | Biograph128                     | VG51B                   |
| SIEMENS             | Biograph128                     | VG51C                   |
| SIEMENS             | Biograph128                     | VG60A                   |
| SIEMENS             | Biograph128                     | VG62B                   |
| SIEMENS             | Biograph128                     | VG70A                   |
| SIEMENS             | Biograph128                     | VG70B                   |
| SIEMENS             | Biograph128                     | VG70C                   |
| SIEMENS             | Biograph128                     | VG76A                   |
| SIEMENS             | Biograph128                     | VG76B                   |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR.  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b> |
|---------------------|---------------------------------|-------------------------|
| SIEMENS             | Biograph128                     | syngo MI.PET/CT 2009C   |
| SIEMENS             | Biograph128                     | syngo MI.PET/CT 2011A   |
| SIEMENS             | Biograph128                     | syngo MI.PET/CT 2012A   |
| SIEMENS             | Biograph128Edge                 | VG70A                   |
| SIEMENS             | Biograph128_mCT                 | VG60A                   |
| SIEMENS             | Biograph20                      | VG50A                   |
| SIEMENS             | Biograph20                      | VG51A                   |
| SIEMENS             | Biograph20                      | VG51B                   |
| SIEMENS             | Biograph20                      | VG51C                   |
| SIEMENS             | Biograph20                      | VG60A                   |
| SIEMENS             | Biograph20                      | VG62B                   |
| SIEMENS             | Biograph20                      | VG70A                   |
| SIEMENS             | Biograph20                      | VG70B                   |
| SIEMENS             | Biograph20                      | VG70C                   |
| SIEMENS             | Biograph20                      | syngo MI.PET/CT 2011A   |
| SIEMENS             | Biograph20                      | syngo MI.PET/CT 2012A   |
| SIEMENS             | Biograph40                      |                         |
| SIEMENS             | Biograph40                      | Unknown                 |
| SIEMENS             | Biograph40                      | VG50A                   |
| SIEMENS             | Biograph40                      | VG51A                   |
| SIEMENS             | Biograph40                      | VG51B                   |
| SIEMENS             | Biograph40                      | VG51C                   |
| SIEMENS             | Biograph40                      | VG60A                   |
| SIEMENS             | Biograph40                      | VG62B                   |
| SIEMENS             | Biograph40                      | VG70A                   |
| SIEMENS             | Biograph40                      | VG70B                   |
| SIEMENS             | Biograph40                      | VG70C                   |
| SIEMENS             | Biograph40                      | syngo MI.PET/CT 2009C   |
| SIEMENS             | Biograph40                      | syngo MI.PET/CT 2011A   |
| SIEMENS             | Biograph40                      | syngo MI.PET/CT 2012A   |
| SIEMENS             | Biograph40_TruePoint            | 6.7.3                   |
| SIEMENS             | Biograph40_TruePoint-1094       | 6.7.3                   |
| SIEMENS             | Biograph40_mCT                  | Unknown                 |
| SIEMENS             | Biograph64                      |                         |
| SIEMENS             | Biograph64                      | VG50A                   |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b>  |
|---------------------|---------------------------------|--------------------------|
| SIEMENS             | Biograph64                      | VG51A                    |
| SIEMENS             | Biograph64                      | VG51B                    |
| SIEMENS             | Biograph64                      | VG51C                    |
| SIEMENS             | Biograph64                      | VG60A                    |
| SIEMENS             | Biograph64                      | VG62A                    |
| SIEMENS             | Biograph64                      | VG62B                    |
| SIEMENS             | Biograph64                      | VG70A                    |
| SIEMENS             | Biograph64                      | VG70B                    |
| SIEMENS             | Biograph64                      | VG70C                    |
| SIEMENS             | Biograph64                      | VG76B                    |
| SIEMENS             | Biograph64                      | syngo MI.PET/CT 2009C    |
| SIEMENS             | Biograph64                      | syngo MI.PET/CT 2011A    |
| SIEMENS             | Biograph64                      | syngo MI.PET/CT 2012A    |
| SIEMENS             | Biograph64_TruePoint-1094       | 6.7.3                    |
| SIEMENS             | Biograph64_mCT                  | VG51A                    |
| SIEMENS             | Biograph64_mCT                  | syngo MI.PET/CT 2012A    |
| SIEMENS             | Biograph6_TruePoint             | 6.7.2                    |
| SIEMENS             | Biograph6_TruePoint             | 6.7.3                    |
| SIEMENS             | Biograph6_TruePoint-1093        | 6.7.2                    |
| SIEMENS             | Definition                      |                          |
| SIEMENS             | Definition                      | syngo CT 2007C           |
| SIEMENS             | Definition                      | syngo CT 2007C.1.03b_P03 |
| SIEMENS             | Definition                      | syngo CT 2008G           |
| SIEMENS             | Definition AS                   |                          |
| SIEMENS             | Definition AS                   | syngo CT 2008G           |
| SIEMENS             | Definition AS                   | syngo CT 2009B           |
| SIEMENS             | Definition AS                   | syngo CT 2009B.1.02_P01  |
| SIEMENS             | Definition AS                   | syngo CT 2010B           |
| SIEMENS             | Definition AS                   | syngo CT 2010B.1.02_P01  |
| SIEMENS             | Definition AS+                  |                          |
| SIEMENS             | Definition AS+                  | syngo CT 2008G           |
| SIEMENS             | Definition AS+                  | syngo CT 2010B           |
| SIEMENS             | DoseWatch                       |                          |
| SIEMENS             | Emotion                         | VA47C                    |
| SIEMENS             | Emotion 16                      |                          |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b> |
|---------------------|---------------------------------|-------------------------|
| SIEMENS             | Emotion 16                      | syngo CT 2006G          |
| SIEMENS             | Emotion 16                      | syngo CT 2007E          |
| SIEMENS             | Emotion 16                      | syngo CT 2013A          |
| SIEMENS             | Emotion 16                      | syngo CT 2014A          |
| SIEMENS             | Emotion 16 (2007)               |                         |
| SIEMENS             | Emotion 16 (2007)               | 6.4                     |
| SIEMENS             | Emotion 16 (2007)               | syngo CT 2007E          |
| SIEMENS             | Emotion 16 (2007)               | syngo CT 2009E          |
| SIEMENS             | Emotion 16 (2007)               | syngo CT 2012E          |
| SIEMENS             | Emotion 16 (2007)               | syngo CT 2014A          |
| SIEMENS             | Emotion 16 (2010)               |                         |
| SIEMENS             | Emotion 16 (2010)               | syngo CT 2012E          |
| SIEMENS             | Emotion 16 (2010)               | syngo CT 2014A          |
| SIEMENS             | Emotion 6                       |                         |
| SIEMENS             | Emotion 6                       | VA70C                   |
| SIEMENS             | Emotion 6                       | VB10B                   |
| SIEMENS             | Emotion 6                       | syngo CT 2006A          |
| SIEMENS             | Emotion 6                       | syngo CT 2007E          |
| SIEMENS             | Emotion 6                       | syngo CT 2014A          |
| SIEMENS             | Emotion 6 (2007)                | syngo CT 2007E          |
| SIEMENS             | Emotion 6 (2007)                | syngo CT 2009E          |
| SIEMENS             | Emotion 6 (2007)                | syngo CT 2014A          |
| SIEMENS             | Emotion 6 (2010)                | syngo CT 2014A          |
| SIEMENS             | Emotion Duo                     | VA40C                   |
| SIEMENS             | Emotion Duo                     | VA45A                   |
| SIEMENS             | Emotion Duo                     | VA47C                   |
| SIEMENS             | Emotion Duo                     | syngo CT 2006A          |
| SIEMENS             | Emotion Duo                     | syngo CT 2007E          |
| SIEMENS             | Emotion Duo                     | syngo CT 2014A          |
| SIEMENS             | Esprit                          | VA47C                   |
| SIEMENS             | Fluorospot Compact FD           | VH11V                   |
| SIEMENS             | Horos                           | syngo CT VA48A          |
| SIEMENS             | OsiriX                          | syngo CT 2009E          |
| SIEMENS             | OsiriX                          | syngo CT 2012B          |
| SIEMENS             | OsiriX                          | syngo CT VA50A          |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**



**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b>         |
|---------------------|---------------------------------|---------------------------------|
| SIEMENS             | Perspective                     |                                 |
| SIEMENS             | Perspective                     | syngo CT 2012A                  |
| SIEMENS             | Perspective                     | syngo CT 2013A                  |
| SIEMENS             | Perspective                     | syngo CT VC28                   |
| SIEMENS             | Perspective                     | syngo CT VC40                   |
| SIEMENS             | SOMATOM Confidence              | syngo CT VB20A                  |
| SIEMENS             | SOMATOM Definition              |                                 |
| SIEMENS             | SOMATOM Definition              | 2.2                             |
| SIEMENS             | SOMATOM Definition              | syngo CT 2010A                  |
| SIEMENS             | SOMATOM Definition              | syngo CT 2010A.1.01c_P00        |
| SIEMENS             | SOMATOM Definition              | syngo CT 2010A.1.03_P01         |
| SIEMENS             | SOMATOM Definition              | syngo CT 2012B                  |
| SIEMENS             | SOMATOM Definition AS           |                                 |
| SIEMENS             | SOMATOM Definition AS           | 2.2                             |
| SIEMENS             | SOMATOM Definition AS           | syngo CT 2011A                  |
| SIEMENS             | SOMATOM Definition AS           | syngo CT 2011A.1_20101022_0_P00 |
| SIEMENS             | SOMATOM Definition AS           | syngo CT 2012B                  |
| SIEMENS             | SOMATOM Definition AS           | syngo CT 2013B                  |
| SIEMENS             | SOMATOM Definition AS           | syngo CT VA48A                  |
| SIEMENS             | SOMATOM Definition AS           | syngo CT VB10A                  |
| SIEMENS             | SOMATOM Definition AS           | syngo CT VB20A                  |
| SIEMENS             | SOMATOM Definition AS           | syngo MI.PET/CT 2012A           |
| SIEMENS             | SOMATOM Definition AS+          |                                 |
| SIEMENS             | SOMATOM Definition AS+          | syngo CT 2011A                  |
| SIEMENS             | SOMATOM Definition AS+          | syngo CT 2011A.1.04_P02         |
| SIEMENS             | SOMATOM Definition AS+          | syngo CT 2011A.1_SP0.2_P10      |
| SIEMENS             | SOMATOM Definition AS+          | syngo CT 2012B                  |
| SIEMENS             | SOMATOM Definition AS+          | syngo CT VA48A                  |
| SIEMENS             | SOMATOM Definition AS+          | syngo CT VB10A                  |
| SIEMENS             | SOMATOM Definition AS+          | syngo CT VB20A                  |
| SIEMENS             | SOMATOM Definition Edge         |                                 |
| SIEMENS             | SOMATOM Definition Edge         | 2.2                             |
| SIEMENS             | SOMATOM Definition Edge         | syngo CT 2012B                  |
| SIEMENS             | SOMATOM Definition Edge         | syngo CT 2012B.1.04_P01         |
| SIEMENS             | SOMATOM Definition Edge         | syngo CT VA48A                  |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b>             |
|---------------------|---------------------------------|-------------------------------------|
| SIEMENS             | SOMATOM Definition Edge         | syngo CT VB10A                      |
| SIEMENS             | SOMATOM Definition Edge         | syngo CT VB20A                      |
| SIEMENS             | SOMATOM Definition Flash        |                                     |
| SIEMENS             | SOMATOM Definition Flash        | syngo CT 2009A                      |
| SIEMENS             | SOMATOM Definition Flash        | syngo CT 2010A                      |
| SIEMENS             | SOMATOM Definition Flash        | syngo CT 2010A.1_P01                |
| SIEMENS             | SOMATOM Definition Flash        | syngo CT 2011A                      |
| SIEMENS             | SOMATOM Definition Flash        | syngo CT 2011A.0.11_P00             |
| SIEMENS             | SOMATOM Definition Flash        | syngo CT 2011A.0_20100726_0_P00     |
| SIEMENS             | SOMATOM Definition Flash        | syngo CT 2011A.1_SP0_20110414_0_P20 |
| SIEMENS             | SOMATOM Definition Flash        | syngo CT 2012B                      |
| SIEMENS             | SOMATOM Definition Flash        | syngo CT 2012B.0_20110718_0_P00     |
| SIEMENS             | SOMATOM Definition Flash        | syngo CT 2012B.1.05_P00             |
| SIEMENS             | SOMATOM Definition Flash        | syngo CT VA48A                      |
| SIEMENS             | SOMATOM Definition Flash        | syngo CT VB20A                      |
| SIEMENS             | SOMATOM Drive                   |                                     |
| SIEMENS             | SOMATOM Drive                   | syngo CT VA62A                      |
| SIEMENS             | SOMATOM Drive                   | syngo CT VB10A                      |
| SIEMENS             | SOMATOM Drive                   | syngo CT VB20A                      |
| SIEMENS             | SOMATOM Edge Plus               |                                     |
| SIEMENS             | SOMATOM Edge Plus               | syngo CT VB10A                      |
| SIEMENS             | SOMATOM Edge Plus               | syngo CT VB20A                      |
| SIEMENS             | SOMATOM Emotion 16              |                                     |
| SIEMENS             | SOMATOM Emotion 16              | syngo CT VC30 - easyIQ version      |
| SIEMENS             | SOMATOM Emotion 6               |                                     |
| SIEMENS             | SOMATOM Force                   |                                     |
| SIEMENS             | SOMATOM Force                   | 2.2                                 |
| SIEMENS             | SOMATOM Force                   | Unknown                             |
| SIEMENS             | SOMATOM Force                   | syngo CT VA50A                      |
| SIEMENS             | SOMATOM Force                   | syngo CT VA50A.1.03_P01             |
| SIEMENS             | SOMATOM Force                   | syngo CT VA50A.1.04_P05             |
| SIEMENS             | SOMATOM Force                   | syngo CT VB10A                      |
| SIEMENS             | SOMATOM Force                   | syngo CT VB20A                      |
| SIEMENS             | SOMATOM Perspective             |                                     |
| SIEMENS             | SOMATOM Perspective             | 2.2                                 |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b>                            |
|---------------------|---------------------------------|--|
| SIEMENS             | SOMATOM Perspective             | syngo CT VC30 - easyIQ version                     |
| SIEMENS             | SOMATOM Perspective             | syngo CT VC40                                      |
| SIEMENS             | SOMATOM Perspective             | syngo CT VC50                                      |
| SIEMENS             | SOMATOM Scope                   | syngo CT VC30 - easyIQ version                     |
| SIEMENS             | SOMATOM Scope                   | syngo CT VC40                                      |
| SIEMENS             | SOMATOM Sensation 16            | 2.2  |
| SIEMENS             | SOMATOM Sensation 40            | 2.2  |
| SIEMENS             | SOMATOM Sensation 64            |  |
| SIEMENS             | SOMATOM Sensation 64            | 2.2  |
| SIEMENS             | SOMATOM go.All                  | VA20A\RELEASE.VA20A.SP0_MSP_20181011_1947.1\RELEAS |
| SIEMENS             | SOMATOM go.All                  | VA20A\RELEASE.VA20A.SP1_MSP_20181204_2053.1\RELEAS |
| SIEMENS             | SOMATOM go.All                  | VA20A\RELEASE.VA20A.SP2A_MSP_20190508_1508.1\RELEA |
| SIEMENS             | SOMATOM go.All                  | VA20A\RELEASE.VA20A.SP2B_MSP_20190607_2010.1\RELEA |
| SIEMENS             | SOMATOM go.All                  | VA20A\RELEASE.VA20A.SP3A_MSP_20191205_1459.1\RELEA |
| SIEMENS             | SOMATOM go.All                  | VA20A\RELEASE.VA20A.SP3_MSP_20190903_0330.1\RELEAS |
| SIEMENS             | SOMATOM go.All                  | VA20A\RELEASE.VA20A.SP4A_MSP_20200305_0748.1\RELEA |
| SIEMENS             | SOMATOM go.All                  | VA20A\RELEASE.VA20A.SP4_MSP_20200205_1936.1\RELEAS |
| SIEMENS             | SOMATOM go.All                  | VA20A\RELEASE.VA20A_GCI_20180522_1940.1\RELEASE.VA |
| SIEMENS             | SOMATOM go.All                  | syngo CT VA30A                                     |
| SIEMENS             | SOMATOM go.Now                  | VA20A\RELEASE.VA20A.SP1_MSP_20181204_2053.1\RELEAS |
| SIEMENS             | SOMATOM go.Now                  | VA20A\RELEASE.VA20A.SP2B_MSP_20190607_2010.1\RELEA |
| SIEMENS             | SOMATOM go.Now                  | VA20A\RELEASE.VA20A.SP3A_MSP_20191205_1459.1\RELEA |
| SIEMENS             | SOMATOM go.Now                  | VA20A\RELEASE.VA20A.SP4A_MSP_20200305_0748.1\RELEA |
| SIEMENS             | SOMATOM go.Top                  | VA20A\RELEASE.VA20A.SP0_MSP_20181011_1947.1\RELEAS |
| SIEMENS             | SOMATOM go.Top                  | VA20A\RELEASE.VA20A.SP1_MSP_20181204_2053.1\RELEAS |
| SIEMENS             | SOMATOM go.Top                  | VA20A\RELEASE.VA20A.SP2A_MSP_20190508_1508.1\RELEA |
| SIEMENS             | SOMATOM go.Top                  | VA20A\RELEASE.VA20A.SP2B_MSP_20190607_2010.1\RELEA |
| SIEMENS             | SOMATOM go.Top                  | VA20A\RELEASE.VA20A.SP2_MSP_20190316_2118.1\RELEAS |
| SIEMENS             | SOMATOM go.Top                  | VA20A\RELEASE.VA20A.SP3A_MSP_20191205_1459.1\RELEA |
| SIEMENS             | SOMATOM go.Top                  | VA20A\RELEASE.VA20A.SP3_MSP_20190903_0330.1\RELEAS |
| SIEMENS             | SOMATOM go.Top                  | VA20A\RELEASE.VA20A.SP4A_MSP_20200305_0748.1\RELEA |
| SIEMENS             | SOMATOM go.Top                  | VA20A\RELEASE.VA20A.SP4_MSP_20200205_1936.1\RELEAS |
| SIEMENS             | SOMATOM go.Top                  | VA20A\RELEASE.VA20A_GCI_20180522_1940.1\RELEASE.VA |
| SIEMENS             | SOMATOM go.Up                   |  |
| SIEMENS             | SOMATOM go.Up                   | RELEASE.VA10A.SP1_MSP_20171116_2012.1              |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b>                            |
|---------------------|---------------------------------|--|
| SIEMENS             | SOMATOM go.Up                   | VA10A._RELEASE.VA10A.SP0_GCI_20170727_1354.2       |
| SIEMENS             | SOMATOM go.Up                   | VA10A._RELEASE.VA10A_GCI_20170405_1240.2           |
| SIEMENS             | SOMATOM go.Up                   | VA20A\RELEASE.VA20A.SP0_MSP_20181011_1947.1\RELEAS |
| SIEMENS             | SOMATOM go.Up                   | VA20A\RELEASE.VA20A.SP1_MSP_20181204_2053.1\RELEAS |
| SIEMENS             | SOMATOM go.Up                   | VA20A\RELEASE.VA20A.SP2B_MSP_20190607_2010.1\RELEA |
| SIEMENS             | SOMATOM go.Up                   | VA20A\RELEASE.VA20A.SP3A_MSP_20191205_1459.1\RELEA |
| SIEMENS             | SOMATOM go.Up                   | VA20A\RELEASE.VA20A.SP3_MSP_20190903_0330.1\RELEAS |
| SIEMENS             | SOMATOM go.Up                   | VA20A\RELEASE.VA20A.SP4A_MSP_20200305_0748.1\RELEA |
| SIEMENS             | SOMATOM go.Up                   | VA20A\RELEASE.VA20A_GCI_20180522_1940.1\RELEASE.VA |
| SIEMENS             | Scope                           | syngo CT VC28                                      |
| SIEMENS             | Sensation 10                    |  |
| SIEMENS             | Sensation 10                    | VA70B  |
| SIEMENS             | Sensation 10                    | VA70C  |
| SIEMENS             | Sensation 10                    | VB10B  |
| SIEMENS             | Sensation 10                    | syngo CT 2006G                                     |
| SIEMENS             | Sensation 16                    |  |
| SIEMENS             | Sensation 16                    | VA70B  |
| SIEMENS             | Sensation 16                    | VA70C  |
| SIEMENS             | Sensation 16                    | VB10B  |
| SIEMENS             | Sensation 16                    | syngo CT 2006G                                     |
| SIEMENS             | Sensation 16                    | syngo CT 2007S                                     |
| SIEMENS             | Sensation 16                    | syngo CT 2014A                                     |
| SIEMENS             | Sensation 16 with Akron Q tube  | syngo CT 2014A                                     |
| SIEMENS             | Sensation 4                     |  |
| SIEMENS             | Sensation 4                     | VA40C  |
| SIEMENS             | Sensation 4                     | VA47C  |
| SIEMENS             | Sensation 40                    |  |
| SIEMENS             | Sensation 40                    | syngo CT 2006A                                     |
| SIEMENS             | Sensation 40                    | syngo CT 2007S                                     |
| SIEMENS             | Sensation 40                    | syngo CT 2009E                                     |
| SIEMENS             | Sensation 40                    | syngo CT 2014A                                     |
| SIEMENS             | Sensation 40                    | xxxxx  |
| SIEMENS             | Sensation 64                    |  |
| SIEMENS             | Sensation 64                    | syngo CT 2006A                                     |
| SIEMENS             | Sensation 64                    | syngo CT 2007S                                     |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b>                            |
|---------------------|---------------------------------|--|
| SIEMENS             | Sensation 64                    | syngo CT 2009E                                     |
| SIEMENS             | Sensation 64                    | syngo CT 2012E                                     |
| SIEMENS             | Sensation 64                    | syngo CT 2014A                                     |
| SIEMENS             | Sensation 64                    | xxxxx  |
| SIEMENS             | Sensation Cardiac               |  |
| SIEMENS             | Sensation Cardiac               | syngo CT 2006G                                     |
| SIEMENS             | Sensation Cardiac               | syngo CT 2007S                                     |
| SIEMENS             | Sensation Cardiac               | syngo CT 2014A                                     |
| SIEMENS             | Sensation Cardiac 64            |  |
| SIEMENS             | Sensation Cardiac 64            | syngo CT 2005A                                     |
| SIEMENS             | Sensation Cardiac 64            | syngo CT 2006A                                     |
| SIEMENS             | Sensation Cardiac 64            | syngo CT 2007S                                     |
| SIEMENS             | Sensation Cardiac 64            | syngo CT 2009E                                     |
| SIEMENS             | Sensation Cardiac 64            | syngo CT 2012E                                     |
| SIEMENS             | Sensation Cardiac 64            | syngo CT 2014A                                     |
| SIEMENS             | Sensation Open                  | syngo CT 2006A                                     |
| SIEMENS             | Sensation Open                  | syngo CT 2007S                                     |
| SIEMENS             | Sensation Open                  | syngo CT 2009E                                     |
| SIEMENS             | Sensation Open                  | syngo CT 2014A                                     |
| SIEMENS             | Sensation Open                  | xxxxx  |
| SIEMENS             | Somaris/7CaScoring              | syngo CT 2011A                                     |
| SIEMENS             | Somaris/7CaScoring              | syngo CT 2012B                                     |
| SIEMENS             | Somaris/7CaScoring              | syngo CT VA48A                                     |
| SIEMENS             | Spirit                          | syngo CT 2005C                                     |
| SIEMENS             | Spirit                          | syngo CT 2006C                                     |
| SIEMENS             | Spirit                          | syngo CT 2010C                                     |
| SIEMENS             | Symbia Intevo 16                | syngo CT 2013A>Symbia Intevo 16>10.0.1410.1602 SP1 |
| SIEMENS             | Symbia Intevo 16                | syngo CT 2013A>Symbia Intevo 16>10.100.1510.1604>V |
| SIEMENS             | Symbia Intevo 16                | syngo CT VC30 - easyIQ version>Symbia Intevo 16>10 |
| SIEMENS             | Symbia Intevo 16                | syngo CT VC30 - easyIQ version>Symbia Intevo 16>10 |
| SIEMENS             | Symbia Intevo 16                | syngo CT VC30 - easyIQ version>Symbia Intevo 16>10 |
| SIEMENS             | Symbia Intevo 16                | syngo CT VC30>Symbia Intevo 16>10.510.1710.306>VB2 |
| SIEMENS             | Symbia Intevo 16                | syngo CT VC30>Symbia Intevo 16>10.510.1710.402>VB2 |
| SIEMENS             | Symbia Intevo 16                | syngo CT VC40>Symbia Intevo 16>VB21A               |
| SIEMENS             | Symbia Intevo 2                 | syngo CT 2013A>Symbia Intevo 2>10.0.1410.1602 SP1> |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b>                            |
|---------------------|---------------------------------|--|
| SIEMENS             | Symbia Intevo 2                 | syngo CT 2013A>Symbia Intevo 2>10.100.1510.1604>VB |
| SIEMENS             | Symbia Intevo 6                 | syngo CT 2013A>Symbia Intevo 6>10.0.1410.1602 SP1> |
| SIEMENS             | Symbia Intevo 6                 | syngo CT 2013A>Symbia Intevo 6>10.100.1510.1604>VB |
| SIEMENS             | Symbia Intevo 6                 | syngo CT VC30 - easyIQ version>Symbia Intevo 6>10. |
| SIEMENS             | Symbia Intevo 6                 | syngo CT VC40>Symbia Intevo 6>VB21A                |
| SIEMENS             | Symbia Intevo Excel             | syngo CT 2013A>Symbia Intevo Excel>10.0.1410.1602  |
| SIEMENS             | Symbia Intevo Excel             | syngo CT 2013A>Symbia Intevo Excel>10.100.1510.160 |
| SIEMENS             | Symbia Intevo Excel             | syngo CT VC40>Symbia Intevo Excel>VB21A            |
| SIEMENS             | Symbia T                        | syngo CT 2007E>Symbia T>8.5.10.6 SP1>VA60A         |
| SIEMENS             | Symbia T                        | syngo CT 2007E>Symbia T>8.5.10.7 SP1>VA60A         |
| SIEMENS             | Symbia T-2008                   | syngo CT 2013A>Symbia T-2008>10.0.1410.1602 SP1>VB |
| SIEMENS             | Symbia T-2008                   | syngo CT 2013A>Symbia T-2008>10.100.1510.1604>VB10 |
| SIEMENS             | Symbia T-2008                   | syngo CT VC40>Symbia T-2008>VB21A                  |
| SIEMENS             | Symbia T16                      | syngo CT 2007E>Symbia T16>7.5.9.5 SP2              |
| SIEMENS             | Symbia T16                      | syngo CT 2007E>Symbia T16>8.1.15.7 SP2             |
| SIEMENS             | Symbia T16                      | syngo CT 2007E>Symbia T16>8.5.10.10 SP3>VA60D      |
| SIEMENS             | Symbia T16                      | syngo CT 2007E>Symbia T16>8.5.10.6 SP1>VA60A       |
| SIEMENS             | Symbia T16                      | syngo CT 2007E>Symbia T16>8.5.10.7 SP1>VA60B       |
| SIEMENS             | Symbia T16                      | syngo CT 2007E>Symbia T16>8.5.10.9 SP2>VA60C       |
| SIEMENS             | Symbia T16                      | syngo CT 2007E>Symbia T16>8.5.11.9 SP0>VA61B       |
| SIEMENS             | Symbia T16                      | syngo CT 2007E>Symbia T16>8.5.11.9 SP3>VA61B       |
| SIEMENS             | Symbia T16                      | syngo CT 2007E>Symbia T16>8.6.3.4 SP1>VA63A        |
| SIEMENS             | Symbia T16                      | syngo CT 2007E>Symbia T16>8.6.3.5 SP1>VA63A        |
| SIEMENS             | Symbia T16                      | syngo CT 2007E>Symbia T16>9.0.31.3 SP1>VA70A       |
| SIEMENS             | Symbia T16                      | syngo CT 2013A>Symbia T16>10.0.1410.1602 SP1>VB10A |
| SIEMENS             | Symbia T16                      | syngo CT 2013A>Symbia T16>10.100.1510.1604>VB10B   |
| SIEMENS             | Symbia T2                       | syngo CT 2007E>Symbia Intevo Excel>9.0.31.3 SP1>VA |
| SIEMENS             | Symbia T2                       | syngo CT 2007E>Symbia T-2008>8.2.26.8 SP3          |
| SIEMENS             | Symbia T2                       | syngo CT 2007E>Symbia T-2008>8.5.10.10 SP3>VA60D   |
| SIEMENS             | Symbia T2                       | syngo CT 2007E>Symbia T-2008>8.5.10.6 SP1>VA60A    |
| SIEMENS             | Symbia T2                       | syngo CT 2007E>Symbia T-2008>8.5.10.7 SP1>VA60B    |
| SIEMENS             | Symbia T2                       | syngo CT 2007E>Symbia T-2008>8.5.10.9 SP2>VA60C    |
| SIEMENS             | Symbia T2                       | syngo CT 2007E>Symbia T-2008>8.5.11.9 SP3>VA61B    |
| SIEMENS             | Symbia T2                       | syngo CT 2007E>Symbia T-2008>9.0.31.3 SP1>VA70A    |
| SIEMENS             | Symbia T2                       | syngo CT 2007E>Symbia T2>8.1.15.7 SP2              |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b>                           |
|---------------------|---------------------------------|---|
| SIEMENS             | Symbia T2                       | syngo CT 2007E>Symbia T2>8.5.10.10 SP3>VA60D      |
| SIEMENS             | Symbia T2                       | syngo CT 2007E>Symbia T2>8.5.10.9 SP2>VA60C       |
| SIEMENS             | Symbia T2                       | syngo CT 2013A>Symbia T2>10.0.1410.1602 SP1>VB10A |
| SIEMENS             | Symbia T2                       | syngo CT 2013A>Symbia T2>10.100.1510.1604>VB10B   |
| SIEMENS             | Symbia T6                       | syngo CT 2007E>Symbia Intevo 6>9.0.31.3 SP1>VA70A |
| SIEMENS             | Symbia T6                       | syngo CT 2007E>Symbia T6>7.5.9.5 SP2              |
| SIEMENS             | Symbia T6                       | syngo CT 2007E>Symbia T6>8.1.15.7 SP2             |
| SIEMENS             | Symbia T6                       | syngo CT 2007E>Symbia T6>8.2.26.5 SP1             |
| SIEMENS             | Symbia T6                       | syngo CT 2007E>Symbia T6>8.2.26.7 SP2             |
| SIEMENS             | Symbia T6                       | syngo CT 2007E>Symbia T6>8.5.10.10 SP3>VA60D      |
| SIEMENS             | Symbia T6                       | syngo CT 2007E>Symbia T6>8.5.10.6 SP1>VA60A       |
| SIEMENS             | Symbia T6                       | syngo CT 2007E>Symbia T6>8.5.10.7 SP1>VA60B       |
| SIEMENS             | Symbia T6                       | syngo CT 2007E>Symbia T6>8.5.10.9 SP2>VA60C       |
| SIEMENS             | Symbia T6                       | syngo CT 2013A                                    |
| SIEMENS             | Symbia T6                       | syngo CT 2013A>Symbia T6>10.100.1510.1604>VB10B   |
| SIEMENS             | Unknown Model                   | Unknown   |
| SIEMENS             | Unknown Model                   | syngo CT 2009E                                    |
| SIEMENS             | Unknown Model                   | syngo CT 2011A                                    |
| SIEMENS             | Unknown Model                   | syngo CT 2012B                                    |
| SIEMENS             | Volume Access                   | VA47C   |
| SIEMENS             | Volume Zoom                     |   |
| SIEMENS             | Volume Zoom                     | VA40C   |
| SIEMENS             | Volume Zoom                     | VA47C   |
| SIEMENS             | petmct1                         | VG60A   |
| SIEMENS             | petmct1                         | syngo MI.PET/CT 2011A                             |
| SIEMENS             | petmct1                         | syngo MI.PET/CT 2012A                             |
| SIEMENS             | syngo.via                       | 1   |
| SIEMENS             | syngo.via                       | VA30A_HF06  |
| SIEMENS             | syngo.via                       | VB10A_HF04  |
| SIEMENS             | syngo.via                       | VB10B_HF01  |
| SIEMENS             | syngo.via                       | VB10B_HF03  |
| SIEMENS             | syngo.via                       | VB10B_HF04  |
| SIEMENS             | syngo.via                       | VB20A_HF01  |
| SIEMENS             | syngo.via                       | VB20A_HF03  |
| SIEMENS             | syngo.via                       | VB20A_HF05  |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b>  | <b>Manufacturers Model Name</b> | <b>Software Version</b>              |
|----------------------|---------------------------------|--------------------------------------|
| SIEMENS              | syngo.via                       | VB30A_HF03                           |
| SIEMENS              | syngo.via                       | VB30A_HF06                           |
| SIEMENS              | syngo.via                       | syngo.PET&CT Oncology 3.10.1611.1401 |
| SIEMENS              | syngo.via                       | syngo.PET&CT Oncology 5.8.1910.1001  |
| SIEMENS              | syngo.via.VA20A                 | Unknown                              |
| SIEMENS              | syngo.via.VA30A                 | Unknown                              |
| SIEMENS              | syngo.via.VB10A                 | Unknown                              |
| SIEMENS              | syngo.via.VB20A                 | Unknown                              |
| SIEMENS              | syngo.via.VB30A                 | Unknown                              |
| SIEMENS              | syngoMMWP                       | VE52A                                |
| SIEMENS              | tbipetct                        | VG51C                                |
| SIEMENS HEALTHCARE   | syngo.via.VB10A                 |                                      |
| SIEMENS HEALTHINEERS | SOMATOM go.All                  | syngo CT VA30A                       |
| SIEMENS HEALTHINEERS | SOMATOM go.Top                  | syngo CT VA30A                       |
| TOSHIBA              |                                 | V6.06ER009                           |
| TOSHIBA              | Activion16                      |                                      |
| TOSHIBA              | Alexion                         |                                      |
| TOSHIBA              | Alexion                         | V6.06ER009                           |
| TOSHIBA              | Aquilion                        |                                      |
| TOSHIBA              | Aquilion                        | 6.4                                  |
| TOSHIBA              | Aquilion                        | Unknown                              |
| TOSHIBA              | Aquilion                        | V1.41ER001                           |
| TOSHIBA              | Aquilion                        | V1.61ER000                           |
| TOSHIBA              | Aquilion                        | V1.62ER006                           |
| TOSHIBA              | Aquilion                        | V1.62ER506                           |
| TOSHIBA              | Aquilion                        | V2.04ER008                           |
| TOSHIBA              | Aquilion                        | V2.04ER508                           |
| TOSHIBA              | Aquilion                        | V3.10ER010                           |
| TOSHIBA              | Aquilion                        | V3.10ER503                           |
| TOSHIBA              | Aquilion                        | V3.20ER001                           |
| TOSHIBA              | Aquilion                        | V3.20ER003                           |
| TOSHIBA              | Aquilion                        | V3.20ER007                           |
| TOSHIBA              | Aquilion                        | V3.20ER010                           |
| TOSHIBA              | Aquilion                        | V3.20ER012                           |
| TOSHIBA              | Aquilion                        | V3.20ER501                           |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**



**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b> |
|---------------------|---------------------------------|-------------------------|
| TOSHIBA             | Aquilion                        | V3.20ER504              |
| TOSHIBA             | Aquilion                        | V3.20ER505              |
| TOSHIBA             | Aquilion                        | V3.20ER510              |
| TOSHIBA             | Aquilion                        | V3.30ER001              |
| TOSHIBA             | Aquilion                        | V3.30ER003              |
| TOSHIBA             | Aquilion                        | V3.33ER001              |
| TOSHIBA             | Aquilion                        | V3.35ER001              |
| TOSHIBA             | Aquilion                        | V3.35ER004              |
| TOSHIBA             | Aquilion                        | V3.35ER006              |
| TOSHIBA             | Aquilion                        | V3.35ER007              |
| TOSHIBA             | Aquilion                        | V3.35ER008              |
| TOSHIBA             | Aquilion                        | V3.35ER010              |
| TOSHIBA             | Aquilion                        | V3.35ER502              |
| TOSHIBA             | Aquilion                        | V3.35ER504              |
| TOSHIBA             | Aquilion                        | V3.35ER506              |
| TOSHIBA             | Aquilion                        | V3.35ER509              |
| TOSHIBA             | Aquilion                        | V3.35ER510              |
| TOSHIBA             | Aquilion                        | V3.38ER005              |
| TOSHIBA             | Aquilion                        | V3.38ER007              |
| TOSHIBA             | Aquilion                        | V3.38ER008              |
| TOSHIBA             | Aquilion                        | V3.50ER000              |
| TOSHIBA             | Aquilion                        | V3.50ER001              |
| TOSHIBA             | Aquilion                        | V3.50ER002              |
| TOSHIBA             | Aquilion                        | V3.50ER003              |
| TOSHIBA             | Aquilion                        | V3.50ER004              |
| TOSHIBA             | Aquilion                        | V4.40ER011              |
| TOSHIBA             | Aquilion                        | V4.51ER010              |
| TOSHIBA             | Aquilion                        | V4.51ER011              |
| TOSHIBA             | Aquilion                        | V4.51ER013              |
| TOSHIBA             | Aquilion                        | V4.52ER008              |
| TOSHIBA             | Aquilion                        | V4.52ER009              |
| TOSHIBA             | Aquilion                        | V4.63ER006              |
| TOSHIBA             | Aquilion                        | V4.63ER007              |
| TOSHIBA             | Aquilion                        | V4.75ER016              |
| TOSHIBA             | Aquilion                        | V4.77ER003              |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b> |
|---------------------|---------------------------------|-------------------------|
| TOSHIBA             | Aquilion                        | V4.77ER006              |
| TOSHIBA             | Aquilion                        | V4.77ER007              |
| TOSHIBA             | Aquilion                        | V4.77UR003              |
| TOSHIBA             | Aquilion                        | V4.77UR006              |
| TOSHIBA             | Aquilion                        | V4.77UR007              |
| TOSHIBA             | Aquilion                        | V4.78ER007              |
| TOSHIBA             | Aquilion                        | V4.83ER000              |
| TOSHIBA             | Aquilion                        | V4.83ER001              |
| TOSHIBA             | Aquilion                        | V4.83ER002              |
| TOSHIBA             | Aquilion                        | V4.83ER003              |
| TOSHIBA             | Aquilion                        | V4.83ER005              |
| TOSHIBA             | Aquilion                        | V4.86ER003              |
| TOSHIBA             | Aquilion                        | V4.86ER005              |
| TOSHIBA             | Aquilion                        | V4.86ER006              |
| TOSHIBA             | Aquilion                        | V4.86ER007              |
| TOSHIBA             | Aquilion                        | V4.86ER008              |
| TOSHIBA             | Aquilion                        | V4.93ER003              |
| TOSHIBA             | Aquilion                        | V4.93ER006              |
| TOSHIBA             | Aquilion                        | V4.93ER007              |
| TOSHIBA             | Aquilion                        | V4.93ER014              |
| TOSHIBA             | Aquilion                        | V4.XXER000              |
| TOSHIBA             | Aquilion                        | V6.00ER004              |
| TOSHIBA             | Aquilion                        | V6.00ER007              |
| TOSHIBA             | Aquilion                        | V6.00ER009              |
| TOSHIBA             | Aquilion                        | V6.00ER010              |
| TOSHIBA             | Aquilion                        | V6.06ER000              |
| TOSHIBA             | Aquilion                        | V6.06ER002              |
| TOSHIBA             | Aquilion                        | V6.06ER004              |
| TOSHIBA             | Aquilion                        | V6.06ER005              |
| TOSHIBA             | Aquilion                        | V6.06ER006              |
| TOSHIBA             | Aquilion                        | V6.06ER008              |
| TOSHIBA             | Aquilion                        | V6.06ER009              |
| TOSHIBA             | Aquilion                        | V6.06ER011              |
| TOSHIBA             | Aquilion                        | V6.06ER012              |
| TOSHIBA             | Aquilion                        | V6.06ER013              |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b> |
|---------------------|---------------------------------|-------------------------|
| TOSHIBA             | Aquilion                        | V6.06ER016              |
| TOSHIBA             | Aquilion                        | V6.06ER019              |
| TOSHIBA             | Aquilion                        | V6.06ER021              |
| TOSHIBA             | Aquilion                        | V6.06ER023              |
| TOSHIBA             | Aquilion                        | V6.06ER024              |
| TOSHIBA             | Aquilion                        | V6.06ER026              |
| TOSHIBA             | Aquilion                        | V6.06ER033              |
| TOSHIBA             | Aquilion                        | V8.32ER006              |
| TOSHIBA             | Aquilion LB                     | 2.2                     |
| TOSHIBA             | Aquilion Lightning              |                         |
| TOSHIBA             | Aquilion Lightning              | V7.02ER006              |
| TOSHIBA             | Aquilion Lightning              | V7.02ER008              |
| TOSHIBA             | Aquilion Lightning              | V7.04ER004              |
| TOSHIBA             | Aquilion Lightning              | V7.04ER008              |
| TOSHIBA             | Aquilion Lightning              | V7.05ER003              |
| TOSHIBA             | Aquilion Lightning              | V7.05ER005              |
| TOSHIBA             | Aquilion Lightning              | V7.05ER008              |
| TOSHIBA             | Aquilion Lightning              | V7.05ER013              |
| TOSHIBA             | Aquilion Lightning              | V7.05ER014              |
| TOSHIBA             | Aquilion Lightning              | V8.40ER007              |
| TOSHIBA             | Aquilion Lightning              | V8.40ER008              |
| TOSHIBA             | Aquilion Lightning              | V8.42ER003              |
| TOSHIBA             | Aquilion Lightning              | V8.42ER005              |
| TOSHIBA             | Aquilion Lightning              | V8.42ER905              |
| TOSHIBA             | Aquilion Lightning              | V8.44ER001              |
| TOSHIBA             | Aquilion Lightning              | V8.44ER003              |
| TOSHIBA             | Aquilion Lightning              | V8.44ER005              |
| TOSHIBA             | Aquilion ONE                    |                         |
| TOSHIBA             | Aquilion ONE                    | Unknown                 |
| TOSHIBA             | Aquilion ONE                    | V4.51ER002              |
| TOSHIBA             | Aquilion ONE                    | V4.63ER000              |
| TOSHIBA             | Aquilion ONE                    | V4.63ER005              |
| TOSHIBA             | Aquilion ONE                    | V4.63ER006              |
| TOSHIBA             | Aquilion ONE                    | V4.74ER004              |
| TOSHIBA             | Aquilion ONE                    | V4.74ER009              |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b> |
|---------------------|---------------------------------|-------------------------|
| TOSHIBA             | Aquilion ONE                    | V4.82ER000              |
| TOSHIBA             | Aquilion ONE                    | V4.82ER001              |
| TOSHIBA             | Aquilion ONE                    | V4.93ER004              |
| TOSHIBA             | Aquilion ONE                    | V4.93ER006              |
| TOSHIBA             | Aquilion ONE                    | V4.93ER010              |
| TOSHIBA             | Aquilion ONE                    | V6.00ER001              |
| TOSHIBA             | Aquilion ONE                    | V6.00ER004              |
| TOSHIBA             | Aquilion ONE                    | V6.00ER007              |
| TOSHIBA             | Aquilion ONE                    | V6.00ER009              |
| TOSHIBA             | Aquilion ONE                    | V6.00ER010              |
| TOSHIBA             | Aquilion ONE                    | V6.05ER001              |
| TOSHIBA             | Aquilion ONE                    | V6.05ER002              |
| TOSHIBA             | Aquilion ONE                    | V6.05ER004              |
| TOSHIBA             | Aquilion ONE                    | V6.05ER006              |
| TOSHIBA             | Aquilion ONE                    | V6.05ER007              |
| TOSHIBA             | Aquilion ONE                    | V6.06ER002              |
| TOSHIBA             | Aquilion ONE                    | V6.06ER004              |
| TOSHIBA             | Aquilion ONE                    | V6.06ER006              |
| TOSHIBA             | Aquilion ONE                    | V6.06ER009              |
| TOSHIBA             | Aquilion ONE                    | V6.06ER010              |
| TOSHIBA             | Aquilion ONE                    | V6.06ER014              |
| TOSHIBA             | Aquilion ONE                    | V6.06ER906              |
| TOSHIBA             | Aquilion ONE                    | V6.06ER909              |
| TOSHIBA             | Aquilion ONE                    | V6.06ER910              |
| TOSHIBA             | Aquilion ONE                    | V6.06ER914              |
| TOSHIBA             | Aquilion ONE                    | V7.00ER003              |
| TOSHIBA             | Aquilion ONE                    | V7.00ER006              |
| TOSHIBA             | Aquilion ONE                    | V7.00GR004              |
| TOSHIBA             | Aquilion ONE                    | V7.03ER002              |
| TOSHIBA             | Aquilion ONE                    | V7.03ER003              |
| TOSHIBA             | Aquilion ONE                    | V7.03ER008              |
| TOSHIBA             | Aquilion ONE                    | V7.03ER009              |
| TOSHIBA             | Aquilion ONE                    | V7.03ER011              |
| TOSHIBA             | Aquilion ONE                    | V7.03ER012              |
| TOSHIBA             | Aquilion ONE                    | V7.03ER014              |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b> |
|---------------------|---------------------------------|-------------------------|
| TOSHIBA             | Aquilion ONE                    | V7.03ER015              |
| TOSHIBA             | Aquilion ONE                    | V7.03ER019              |
| TOSHIBA             | Aquilion ONE                    | V7.03ER026              |
| TOSHIBA             | Aquilion ONE                    | V7.03ER715              |
| TOSHIBA             | Aquilion ONE                    | V7.03ER719              |
| TOSHIBA             | Aquilion ONE                    | V7.03ER915              |
| TOSHIBA             | Aquilion ONE                    | V7.03ER919              |
| TOSHIBA             | Aquilion ONE                    | V7.30ER004              |
| TOSHIBA             | Aquilion ONE                    | V7.30ER006              |
| TOSHIBA             | Aquilion ONE                    | V8.30ER004              |
| TOSHIBA             | Aquilion ONE                    | V8.30ER904              |
| TOSHIBA             | Aquilion ONE                    | V8.32ER001              |
| TOSHIBA             | Aquilion ONE                    | V8.32ER002              |
| TOSHIBA             | Aquilion ONE                    | V8.32ER003              |
| TOSHIBA             | Aquilion ONE                    | V8.32ER005              |
| TOSHIBA             | Aquilion ONE                    | V8.32ER006              |
| TOSHIBA             | Aquilion ONE                    | V8.32ER007              |
| TOSHIBA             | Aquilion ONE                    | V8.32ER009              |
| TOSHIBA             | Aquilion ONE                    | V8.32ER010              |
| TOSHIBA             | Aquilion ONE                    | V8.32ER012              |
| TOSHIBA             | Aquilion ONE                    | V8.32ER905              |
| TOSHIBA             | Aquilion ONE                    | xxxxx                   |
| TOSHIBA             | Aquilion ONE Family             |                         |
| TOSHIBA             | Aquilion ONE Family             | 2.2                     |
| TOSHIBA             | Aquilion PRIME                  |                         |
| TOSHIBA             | Aquilion PRIME                  | Unknown                 |
| TOSHIBA             | Aquilion PRIME                  | V4.74ER004              |
| TOSHIBA             | Aquilion PRIME                  | V4.82ER000              |
| TOSHIBA             | Aquilion PRIME                  | V4.93ER005              |
| TOSHIBA             | Aquilion PRIME                  | V4.93ER006              |
| TOSHIBA             | Aquilion PRIME                  | V4.93ER009              |
| TOSHIBA             | Aquilion PRIME                  | V4.93ER010              |
| TOSHIBA             | Aquilion PRIME                  | V4.93ER011              |
| TOSHIBA             | Aquilion PRIME                  | V4.93ER014              |
| TOSHIBA             | Aquilion PRIME                  | V5.00ER008              |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b> |
|---------------------|---------------------------------|-------------------------|
| TOSHIBA             | Aquilion PRIME                  | V5.00ER009              |
| TOSHIBA             | Aquilion PRIME                  | V5.00ER011              |
| TOSHIBA             | Aquilion PRIME                  | V5.00ER015              |
| TOSHIBA             | Aquilion PRIME                  | V5.00ER903              |
| TOSHIBA             | Aquilion PRIME                  | V6.00ER006              |
| TOSHIBA             | Aquilion PRIME                  | V6.00ER010              |
| TOSHIBA             | Aquilion PRIME                  | V6.04ER002              |
| TOSHIBA             | Aquilion PRIME                  | V6.04ER003              |
| TOSHIBA             | Aquilion PRIME                  | V6.04ER005              |
| TOSHIBA             | Aquilion PRIME                  | V6.04ER006              |
| TOSHIBA             | Aquilion PRIME                  | V6.06ER001              |
| TOSHIBA             | Aquilion PRIME                  | V6.06ER002              |
| TOSHIBA             | Aquilion PRIME                  | V6.06ER003              |
| TOSHIBA             | Aquilion PRIME                  | V6.06ER004              |
| TOSHIBA             | Aquilion PRIME                  | V6.06ER005              |
| TOSHIBA             | Aquilion PRIME                  | V6.06ER006              |
| TOSHIBA             | Aquilion PRIME                  | V6.06ER009              |
| TOSHIBA             | Aquilion PRIME                  | V7.03ER003              |
| TOSHIBA             | Aquilion PRIME                  | V7.03ER005              |
| TOSHIBA             | Aquilion PRIME                  | V7.03ER008              |
| TOSHIBA             | Aquilion PRIME                  | V7.03ER009              |
| TOSHIBA             | Aquilion PRIME                  | V7.03ER011              |
| TOSHIBA             | Aquilion PRIME                  | V7.03ER012              |
| TOSHIBA             | Aquilion PRIME                  | V7.03ER013              |
| TOSHIBA             | Aquilion PRIME                  | V7.03ER014              |
| TOSHIBA             | Aquilion PRIME                  | V7.03ER015              |
| TOSHIBA             | Aquilion PRIME                  | V7.03ER017              |
| TOSHIBA             | Aquilion PRIME                  | V7.03ER018              |
| TOSHIBA             | Aquilion PRIME                  | V7.03ER019              |
| TOSHIBA             | Aquilion PRIME                  | V7.03ER719              |
| TOSHIBA             | Aquilion PRIME                  | V8.20ER009              |
| TOSHIBA             | Aquilion PRIME                  | V8.20ER011              |
| TOSHIBA             | Aquilion PRIME                  | V8.20ER012              |
| TOSHIBA             | Aquilion PRIME                  | V8.20ER013              |
| TOSHIBA             | Aquilion PRIME                  | V8.20ER014              |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b>                      |
|---------------------|---------------------------------|--|
| TOSHIBA             | Aquilion Precision              | Unknown                                      |
| TOSHIBA             | Aquilion Precision              | V8.61ER006                                   |
| TOSHIBA             | Aquilion Precision              | V8.80ER008                                   |
| TOSHIBA             | Aquilion Prime SP               | Unknown                                      |
| TOSHIBA             | Aquilion Prime SP               | V10.20ER002                                  |
| TOSHIBA             | Aquilion Prime SP               | V10.20ER004                                  |
| TOSHIBA             | Aquilion Prime SP               | V8.41ER005                                   |
| TOSHIBA             | Aquilion Prime SP               | V8.42ER001                                   |
| TOSHIBA             | Aquilion Prime SP               | V8.42ER002                                   |
| TOSHIBA             | Aquilion Prime SP               | V8.42ER005                                   |
| TOSHIBA             | Aquilion Prime SP               | V8.42ER007                                   |
| TOSHIBA             | Aquilion Prime SP               | V8.42ER008                                   |
| TOSHIBA             | Aquilion Prime SP               | V8.42ER905                                   |
| TOSHIBA             | Aquilion Prime SP               | V8.42ER907                                   |
| TOSHIBA             | Aquilion Prime SP               | V8.42ER908                                   |
| TOSHIBA             | Aquilion Prime SP               | V8.44ER001                                   |
| TOSHIBA             | Aquilion/LB                     |  |
| TOSHIBA             | Aquilion/LB                     | Unknown                                      |
| TOSHIBA             | Aquilion/LB                     | V3.35ER006                                   |
| TOSHIBA             | Aquilion/LB                     | V3.50ER002                                   |
| TOSHIBA             | Aquilion/LB                     | V3.50ER004                                   |
| TOSHIBA             | Aquilion/LB                     | V4.94ER008                                   |
| TOSHIBA             | Aquilion/LB                     | V4.94ER009                                   |
| TOSHIBA             | Aquilion/LB                     | V6.06ER009                                   |
| TOSHIBA             | Asteion                         |  |
| TOSHIBA             | Asteion                         | 4.1.0.0\                                     |
| TOSHIBA             | Asteion                         | V1.60ER002                                   |
| TOSHIBA             | Celesteion                      | Unknown                                      |
| TOSHIBA             | Celesteion                      | V6.21ER004                                   |
| TOSHIBA             | Celesteion                      | V6.22ER000                                   |
| TOSHIBA             | Celesteion                      | V6.22ER002                                   |
| TOSHIBA             | Celesteion                      | V6.22ER006                                   |
| TOSHIBA             | SafeCT                          | V4.77ER007\V1.2.51\MV_GID_1\Abdomen/Pelvis 5 |
| TOSHIBA             | Unknown Model                   | Unknown                                      |
| TOSHIBA             | Unknown Model                   | V4.51ER013                                   |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**

**Scanner models that have successfully transmitted files to the DIR  
As of November 2, 2020**

| <b>Manufacturer</b> | <b>Manufacturers Model Name</b> | <b>Software Version</b> |
|---------------------|---------------------------------|-------------------------|
| UIH                 | uCT 760                         | R001                    |
| UIH                 | uCT 780                         | R001                    |
| UIH                 | uEXPLORER                       | R001                    |
| VITAL IMAGES        | Vitrea                          | 6.7.3039.2              |
| VITAL IMAGES, INC   | Vitrea 2                        | Unknown                 |
| VITAL IMAGES, INC.  | Vitrea                          | 6.1.1102.7174           |
| VITAL IMAGES, INC.  | Vitrea                          | 6.2.2096.9290           |
| VITAL IMAGES, INC.  | Vitrea                          | 6.4.2077.184            |
| VITAL IMAGES, INC.  | Vitrea                          | 6.4.4083.268            |
| VITAL IMAGES, INC.  | Vitrea                          | 6.5.3046.1              |
| VITAL IMAGES, INC.  | Vitrea                          | 6.7.1030.1              |
| VITAL IMAGES, INC.  | Vitrea                          | 6.7.3039.2              |
| VITAL IMAGES, INC.  | Vitrea                          | 6.7.4074.1              |
| VITAL IMAGES, INC.  | Vitrea                          | 6.7.6001.1              |
| VITAL IMAGES, INC.  | Vitrea                          | 6.8.109.1               |
| VITAL IMAGES, INC.  | Vitrea                          | Unknown                 |
| VITAL IMAGES, INC.  | Vitrea                          | gmp_hde.74              |
| VIZ.AI              | SOMATOM Definition Edge         | syngo CT VA48A          |
| VIZ.AI              | SOMATOM Force                   | syngo CT VA50A          |
| VIZ.AI              | SOMATOM Force                   | syngo CT VB20A          |
| XORAN TECHNOLOGIES  | MiniCAT                         | 5.4.2                   |

**This list includes models/versions that have successfully transmitted files to the DIR.  
Absence from the list does not necessarily indicate that files cannot be received.**